

HP PageWide Managed Color MFP P77440 and P779xx series Firmware Readme

Product Name(s):

- HP PageWide Managed Color P77440dn
- HP PageWide Managed Color P77940dn
- HP PageWide Managed Color P77940dns
- HP PageWide Managed Color P77940dn+ (Firmware 4.6.4 or newer)
- HP PageWide Managed Color P77950dn
- HP PageWide Managed Color P77950dns
- HP PageWide Managed Color P77960dn
- HP PageWide Managed Color P77960dns

• **Model Number(s):** Y3Z60A, Y3Z61A, Y3Z64A, Y3Z65A, Y3Z62A, Y3Z66A, Y3Z63A, Y3Z68A

This document contains information for the firmware revision number:

Firmware Datecode: 20200808

Firmware Revision: 2411097_060499

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.11.0.1

Reminder: Dynamic security enabled printer. This Firmware includes dynamic security measures, which may prevent supplies with non-HP chips or circuitry from working now or in the future. More at: www.hp.com/go/learnaboutesupplies.

Description

- What is included in the Firmware bundle?
- Who needs this firmware?
- Determining the current version level of your firmware

Enhancements and Fixes provided with this firmware revision

Enhancements and Fixes provided with the previous revision(s)

Installation Instructions

- Additional Information to know
- Using the Embedded Web Server
- Using the Walk up USB port
- Web JetAdmin

FutureSmart Level Switching Procedures

- Embedded Web Server (EWS)
- Device Control Panel
- Web JetAdmin

System Requirements

Technical Assistance

Customer Support

Internet

Additional Information

Legal Statements

- Trademark Notices
- OPEN-SOURCE SOFTWARE LICENSE AGREEMENTS (In English)
- License and Copyright

Description

This Readme file provides specific installation instructions and other information you should know before you perform a firmware update for your HP LaserJet Series printer or MFP. Installation instructions are provided for Single and Multiple Printer Updates.

This document provides specific update, installation and troubleshooting information. For additional information on the device features, refer to the online user guide found on the Windows Printing System Installer CD-ROM that came with your printer or at hp.com.

What is included in a Firmware bundle?

The HP LaserJet printer firmware update file available from the HP web site contains firmware for the printer, embedded JetDirect (if applicable), HP paper handling accessories used with the device in one convenient download file. When the Remote Firmware Upgrade file is sent to the HP LaserJet Printer or MFP firmware for the engine and all connected accessories are upgraded.

Who needs this firmware?

Similar to HP Inc. providing improved software for your HP LaserJet Printer or MFP, HP Inc. provides firmware updates for your printer periodically through its supported lifecycle. A firmware update may be necessary if it is determined that you may benefit from the resolution of any issue that is documented below. These updates are available on the HP support web site.

Determining the current version level of your firmware

To determine the current level of firmware installed on the device:

Go to the printer's or MFP's control panel.

1. Go to the printer's control panel.
2. Swipe left and select the **Reports** application.
3. Select the **Configuration/Status Pages** menu.
4. Select the **Configuration Page** option.
5. Select the **Print**.

On the printed Configuration page look in the section marked "Device Information" for the Firmware Datecode and Firmware Revision. The Firmware Datecode and Firmware Revision will look something like this:

Firmware Revision: 2406029_028982
Firmware Datecode: 20180425

IMPORTANT NOTE:

This firmware file requires an interactive update method. You CANNOT update these Product(s)/Model(s) using the traditional FTP, LPR or Port 9100 methods of upgrading. Please use one of the following methods listed below to update the firmware of this device.

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20200808

Firmware Revision: 2411097_060499

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.11.0.1

For information on HP Security Bulletins addressed by firmware releases, please visit:

<https://support.hp.com/security-bulletins>

To initiate a subscription to receive future HP Security Bulletin alerts via email, visit:

<https://www.hp.com/go/alerts>

ENHANCEMENT:

Base:

- Added device level notifications, such as paper out messages, to be displayed in the Workpath notification area.
- Added support for both the HP and Honeywell barcode reader to allow input text at the control panel by reading a barcode.

Digital Sending:

- No New Updates

Security/Authentication:

- The Embedded Web Server Security Log now provides access to device generated Syslog event information. The log stores all generated syslog event messages to an internal file that can be exported from the device EWS Security page.
- Added support for the HP Smartcard NIPRNet Solution for US Government to now authenticate automatically using the Signature or PIV-Authentication certificate. The preferred certificate for authentication is configured using the Prefer-GSC-IS over PIV card setting.

Embedded JetDirect:

- No New Updates

Analog Fax:

- Added support for Mixed Originals for fax job with pages longer than 15 inches in length.

FIXES:

Base:

- No New Updates
- Jobs may not get duplexed when media is loaded short edge feed in certain cases.
- The Date and Time stamp within the Service Event logs can be different compared to the actual time, depending upon the time zone the printer is set to.
- The device status of "Printer is low on toner/ink" displays in the Window's printer spooler when a long-life consumable, such as an image drum or fuser, is in a low status.
- Scanning from 3rd Party TWAIN application takes longer than expected
- When using the physical keyboard a press of the "Z" key will populate the screen with a "y" in the email field when using the Polish language..
- HP Web Services Tab is missing from device's Embedded Web Server.
- 49.4A.04 error may occur intermittently when printing from certain types of customized applications.
- Some media type strings are displayed incorrectly in Japanese language.
- The device may stop processing groups of mixed copy/print jobs when Serverless Job Accounting/Local Quota is enabled.
- If an export file is created with the Import/Export feature where the "Local quota and job accounting settings" is checked and the "Local Quota" setting in the Embedded Web Server (EWS) is disabled (EWS > General > Quota Settings >

- Local Quota) then the "Local Quota" setting in the EWS will no longer be available in the EWS after the import.
- A device administrator may be unable to access secured Embedded Web Server features when a third-party Authorization proxy is registered.
 - The device may enter sleep state even though the option has been disabled.
 - A 49.DE.05 may occur when HPAC OXP is used in heavy volumes.
 - A "Copier disabled. Check copy control device" message appears on control panel when a FIH accessory is connected, but insufficient copy credits are available.
 - Card Reader may fail after a power cycle and will require the device to be registered again before it works.
 - The configured auto-launch application may fail to launch if the user language is changed when signing in.
 - Japanese Localization for "Retry the Job" is incorrect for email notification.
 - A 49.4A.04 error may occur when printing certain types of PostScript files.
 - The Job Log does not display the full name of a Printed job.
 - Device hangs with a "JetAdvantage Link is Loading" message on the control panel when a kiosk app is uninstalled and then reinstalled without a reboot.
 - Workpath based apps may intermittently fail to load due to a boot time race condition.
 - Several PrintMarkerStatus supply OIDs are missing after upgrade to FutureSmart Firmware Bundle version 4.10.
 - Certain Workpath apps may displayed a different time on the home screen when compared to the Date/Time settings within the Embedded Web Server.
 - Granted permission may not work properly after upgrading when using certain Workpath apps.
 - The Copy Quality setting within Expert Copy is not able to be locked even if it is locked within the Access Control copy menu.

Digital Sending:

- When performing a scan to USB or scan to email, with the "Automatically Straighten" option enabled, the output image is shifted up towards the top of the page.
- The Digital Send file name generated is incorrect when using the device date and time suffix along with the preview option.
- The "Send test Email" function of the Control Panel Setup for Scan to Email always fails with "SMTP Gateway not responding" when an SSL/TLS connection on port 465 is configured.
- An A4/Letter original may be incorrectly detected as an A3/Leger size when scanning from the glass.

Security/Authentication:

- Uses NTLM for authentication when SmartCard authentication is specified

- Scan to folder is sending unsigned packets when the server sets the "Signing Enabled" flag.
- An intermittent 33.05.18 Security Alert may occur during a device power cycle.
- The HPAC app may launch prior to SIO Authentication and storing previous saved credentials in the Cloud Vault.
- LDAP with secure connection fails on server with Channel Binding enabled
- Scan to DFS Folder may stop working, but may recover if enough time passes or printer is rebooted.
- In a network trace there will be no Tree Connect after successful Session Setup packet when scanning to a DFS folder.
- A corresponding Event Log entry is not created when a Syslog event message is sent for a Potential Intrusion Detection event.
- When scanning to a DFS share, a network trace shows "Bad network name" response to Tree Connect packet.

Embedded JetDirect:

- The device may become unresponsive in the morning or after long idle periods which will require a power cycle.
- The device is unable to make a connection to HP Command Center even though the printer is online.
- The Current Settings page when printed in the Polish language is using incorrect structure and words.
- The connection screen in Polish language is not localized correctly.
- Web JetAdmin and HP Security Manager can't remediate SNMPv1/2 credentials when WiFi Direct is enabled
- The Remote Control Panel feature will not load properly when using a Remote Embedded Web Server session over a Cloud Connected, Virtual JetAdvantage Management Connector (VJAMc), device.
- Scan to Email will not work when using an Amazon email server.

Analog Fax:

- Sending 3 or more continuous IP fax jobs may result in a Communication Error.
- Incoming faxes fail to connect after being answered by the MFP
- Fax speed dials with pauses (,) in the fax numbers cannot be restored after being exported.
- Unable to block fax numbers with spaces and hyphen.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20200808
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2411097_060499

Embedded JetDirect	JSI24110014
CPB - Copy Processor Board	3.409
SCB - Scan Control Board	xxxxFA2025AR 1.0
Stapler/Stacker Finisher	LFP1N0062011A00
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.11.0.1
MD5 checksum for .bdl file	c39e9dc003d17ba7b5ffdc40f938d3df

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20200205

Firmware Revision: 2410035_055376

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.10.0.1

For information on HP Security Bulletins addressed by firmware releases, please visit:

<https://support.hp.com/security-bulletins>

To initiate a subscription to receive future HP Security Bulletin alerts via email, visit:

<https://www.hp.com/go/alerts>

ENHANCEMENT:

Base:

- No New Updates

Digital Sending:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

FIXES:

Base:

- Several PrintMarkerStatus supply OIDs are missing after upgrade to FutureSmart Firmware Bundle version 4.10.

Digital Sending:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

Analog Fax:

- No New Updates

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20200205
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2410035_055376
Embedded JetDirect	JSI24100003
CPB - Copy Processor Board	3.407
SCB - Scan Control Board	xxxxFA1941AR 1.0
Stapler/Stacker Finisher	LFP1N0061947A00
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.10.0.1
MD5 checksum for .bdl file	701d64b30e54ca3ecfd9203a646fb2a8

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20191224

Firmware Revision: 2410028_055027

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.10

For information on HP Security Bulletins addressed by firmware releases, please visit:

<https://support.hp.com/security-bulletins>

To initiate a subscription to receive future HP Security Bulletin alerts via email, visit:

<https://www.hp.com/go/alerts>

ENHANCEMENT:

Base:

- Import and export functionality was extended to include more settings: Home Screen, Job apps, Contacts, Accounts and permissions, Energy/sleep, Local quota and Job accounting settings, and Manage trays settings.

Digital Sending:

- No New Updates

Security/Authentication:

- The default setting for "Allow firmware updates sent as print jobs (Port 9100)" has changed to Disabled (previously Enabled).

Embedded JetDirect:

- Added the SLP keep alive setting to the Embedded Web Server's Networking Settings menu.

FIXES:

Base:

- A 49.DE.03 or 49.DE.05 error may occur in a high usage area and an OXP solution is installed.
- Unable to use an Alternate Login when Enable Pre Prompt Check is Enabled for the Default Login Method.
- Monochrome print jobs may not be restricted properly based upon the available quota credits when the Local Quota Service is enabled.
- JetAdvantage Link Apps are presented to the user in the incorrect language when device language is set to Norwegian.

- Printer does not boot to a Ready status and continues to count up endlessly in the Initialization process.
- An "Unknown conflict" warning will appear on the control panel when the Display language is set to Norwegian.
- Incorrect localization with Expert Copy screens.
- Slower than expected print speeds may occur when printing PDF files at 1200dpi with the HP Universal Printer Driver PostScript.
- A "LOCALIZATION ERROR" occurs after upgrading from FutureSmart 3 and changing any setting within the Embedded Web Server's Copy/Print>Default Print Options menu.
- The device status of "Printer is low on toner/ink" displays in the Window's printer spooler when a long-life consumable, such as an image drum or fuser, is in a low status.
- The Home button does not work when a Workpath application is installed.
- The PORT command in the Scan to Active FTP mode contains a null IP address.
- The Print List button to print a list of all the stored jobs is translated incorrectly in German.

Digital Sending:

- No New Updates

Security/Authentication:

- User group permissions may not work in the Embedded Web Server once an OXPd Authorization Agent is loaded.
- "The network folder path specified does not exist" warning is seen on the control panel when scanning to a shared folder with networks that are not configured with a DNS server.

Embedded JetDirect:

- A Back up and Restore will fail to complete successfully if an administrator first accesses the HP Webservices Smart Cloud Tab within the Embedded Web Server.
- SNMPv3 fails to respond when the device is in a power save mode with certain configuration options being set.

Analog Fax:

- The left half of the Fax application control panel screen is missing.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20191224
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2410028_055027
Embedded JetDirect	JSI24100002
CPB - Copy Processor Board	3.407
SCB - Scan Control Board	xxxxFA1941AR 1.0
Stapler/Stacker Finisher	LFP1N0061947A00
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.10
MD5 checksum for .bdl file	f71cc38626e9221a544e180ebde262fc

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20191024

Firmware Revision: 2409058_053389

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.9.0.1

ENHANCEMENT:

Base:

- Added the ability to perform an Auto Reboot when a 61.00.00 error occurs.

Digital Sending:

- No New Updates

Security/Authentication:

- Added support for both Whitelisting and Non-Whitelisting for SIO (Sign In Once) Enablement through HP Command Center.

Embedded JetDirect:

- No New Updates

FIXES:

Base:

- A 49.DE.11 error may occur when retrieving a stored job when the "Assist users to their job" setting is enabled.
- A 66.B5.32 may occur due to the cooling fan stalling within the z+ models.

Digital Sending:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

Analog Fax:

- No New Updates

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20191024
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2409058_053389
Embedded JetDirect	JSI24090014
CPB - Copy Processor Board	3.406
SCB - Scan Control Board	xxxxFA1931AR 1.0
Stapler/Stacker Finisher	LFP1N0061931H00
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.9.0.1
MD5 checksum for .bdl file	7a972fbb729199316334482100c722d6

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20190925

Firmware Revision: 2409049_052979

ENHANCEMENT:

Base:

- Added the ability to process Print, Copy, Scan and Stored jobs simultaneously when Serverless Job Accounting is enabled.
- Added a "Grand Total" row on the Usage Page to sum up the Print, Copy and Fax Equivalent Impressions for Letter/A4 pages.
- Job Accounting performance improvements have been made which modifies the database to return the records in a "Last-In-First-Out" (LIFO) format.
- Added the ability to allow the printer to wake from sleep/standby mode when swiping a digital badge on an attached security card reader.
- Solution whitelisting has been removed. All OXPd and Level 1 Embedded solutions are now supported.
- Added the ability to schedule a restart under the Embedded Web Server (EWS) Troubleshooting menu to allow users to restart a device at a specific time and frequency.

Digital Sending:

- Added support for the Universal Fax Driver which has replaced the legacy PC Send Fax Driver.

Security/Authentication:

- No New Updates

Embedded JetDirect:

- Increased the number of allowable IPv4 addresses within the Access Control List (ACL) to 20 entries.

FIXES:

Base:

- The Print Assembly Report will not print while the control panel is configured in certain languages.

- The Copy, Scan or Print functionality may still be accessible while a user is signing out of the device.
- The Image Preview is not displayed when retrieving stored print jobs from the device control panel.
- A prompt for a different size of media may occur when the input tray has been configured for a custom-size media and tray runs out of paper.
- Certain PDF files may print slowly, when printed directly via USB, the Embedded Web Server, or other direct-print workflows.
- Certain PDF files may print slower than anticipated from the Apple Preview application using the Apple Airprint driver in macOS 10.13 and macOS 10.14.
- Personal Jobs can be retrieved multiple times when using an Encrypted Password.
- The wrong keyboard layout is displayed for the Polish language.
- The Custom Control Panel Wallpaper image is erased when upgrading to FutureSmart Firmware Bundle Version 4.8 or 4.8.0.1.
- The Image Registration Test Page does not print when the device control panel is localized to any language other than English.
- An Acrobat Reader error may appear on the computer screen when opening a PDF in Acrobat Reader DC if the PDF is generated by an HP Digital Sending application and the media is loaded in the short edge feed direction.
- A 49.DE.15 low memory error may occur due to a caching issue when logging In and Out of some third party solutions.
- The Embedded Web Server (EWS) permissions are being grayed out when an OXPd authentication agent proxy is configured.

Digital Sending:

- A user's credentials are being requested a second time when accessing nested subfolders within a Send to Network Folder job.
- The Digital Send file name generated is incorrect when using the device date and time suffix along with the preview option.

Security/Authentication:

- An "Access Denied" error may occur when using a simple hostname in the folder path for the Scan to Folder setup.
- The Authorization Agent registration may fail when the Embedded Web Server (EWS) Access Control "Device Guest" has permissions enabled.

Embedded JetDirect:

- Incorrect characters are displayed on the Network Configuration Page when the control panel is set to Czech or other Latin languages.
- Slow printing may occur when performing direct-PDF printing and when printing certain file types within the Macintosh environment.

- Pages may be missing and not printed when IPP/IPPS jobs are sent in rapid succession.

Analog Fax:

- No New Updates
- The first incoming fax after a reboot may not get answered.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20190925
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2409049_052979
Embedded JetDirect	JSI24090013
CPB - Copy Processor Board	3.406
SCB - Scan Control Board	xxxxFA1931AR 1.0
Stapler/Stacker Finisher	LFP1N0061931F00
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.9
MD5 checksum for .bdl file	121df69fef56655e239181b57351e395

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20190614

Firmware Revision: 2408067_049156

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.8

ENHANCEMENT:

Base:

- Added a recursive query to get all the user members from a group to provide sub groups Permission Set.
- Added the ability to change the font color and effects to improve readability in Home Screen applications.
- Added functionality that would restrict an end user from entering the copy application without credits when using a FIH (Foreign Interface Harness) solution.
- Added the ability to see Faxing and Printing status on the Control Panel while the process is taking place.

- Added the ColorSave feature, which replaces General Office mode when enabled. This feature will require the purchase of an LPD license and is only available for North America.
- Added support for the HP Custom Color Manager Software tool. The tool provides color management capabilities to optimize color printing to better match customer's needs.

Digital Sending:

- Added the ability to manually adjust the scaling of an ADF scanned image in the feed direction.
- Added new naming formats of the scanned file in Scan to Network folder (%DEVICE_HOSTNAME_PQDN%,%DEVICE_DATE_YYMMDD%)

Security/Authentication:

- Added middleware support for SafeNet AT SC650 v4.1t smartcard.

Embedded JetDirect:

- No New Updates

FIXES:

Base:

- Entering a PIN number for a stored job will unlock stored Jobs of another user with the same PIN number.
- Printer may hang when MPI IPDS printing.
- The Cancel button is not correctly notifying authentication solutions at sign-in when user presses the cancel button.
- Copying Legal sized media may get clipped when using the Copy Client from OXPd 1.8.
- A false jam may occur when duplexing custom media sizes with the length between 14 and 17 inches (356 and 432 milimeters).
- Jobs may not get duplexed when media is loaded short edge feed in certain cases.
- Job is cancelled after swiping badge and logging out immediately after scan completes.
- Text may not print in the proper orientation when printing on Envelope Chou#3 size media.
- HP Web JetAdmin might not be able to correctly identify the printer within its firmware repository.

- The pin field pops up on the control panel after a card is inserted with certain Smartcard solutions.
- Certain color PDF documents do not print correctly when using the UPD driver.
- When printing certain PDF files, the printer may output random characters or the actual PDF print code rather than the PDF file as expected.
- Jobs get cancelled immediately instead of waiting for the inactivity timer if the menu item "Delete job on unattended errors" is enabled.
- Not able to log in to the printer if the Sign in button is pressed before using a card authentication method.
- Barcodes are not printed properly in some documents during direct PDF printing.
- An Empty keyboard screen appears after an user authentication is initiated by pressing the "Number of Copies" field of the Copy application button in the device home screen.
- An incorrect translation occurs when registering your device to the Google Cloud Print server.
- LDAP access requests using SSL with CA certificates fail.
- The Expert Copy feature has been temporarily disabled for an user experience redesign and will be reenabled in a future firmware release.

Digital Sending:

- Scan to Email jobs do not complete when scanning with A4 short edge feed media along with other certain settings.
- Text highlighting is incorrectly displayed when searching for text in scanned PDFs with OCR.
- Only 10 email addresses are visible when selecting an email group.
- An Incorrect file name will appear in the Metadata XML file when performing a Send to Network Folder job.

Security/Authentication:

- Unhandled exception causes device to crash with 49.38.07 error immediately after Windows authentication.
- A 49.38.1B error may occur when using an invalid\offline HTTPS Device Alert endpoint.
- Safenet AT SC650 v4.1 card Smart Card: unique provisioning method prevents the middleware from finding the certificates.
- A CA signed ID certificate is replaced with a printer generated self-signed ID certificate when upgrading from FutureSmart 4.5.6 (or newer) to FutureSmart 4.7.3 (or older).
- The default settings for the TLS 1.0 / TLS 1.1 (Transport Layer Security) protocol changed to Disabled (previously Enabled).
 - IMPORTANT NOTE: TLS 1.0 may need to be enabled / re-enabled to be compatible with some HP and 3rd party solutions and legacy web browsers

Embedded JetDirect:

- IPv6 DHCP request packet contains a null Identity Association (IA). This works with the RFC and MS servers, but QIP servers do not handle this well.
- A printer performance slow down may occur with excessive mDNS traffic on a network.
- A stapled document will hang the printer when printing through the Google Cloud print solution.
- The default paper size may be incorrect when using the Google Cloud Print Driver.
- Jobs may not print when sending data over the 9100 port and the printer is in an idle state.
- UDP port 500 responds with an "Informational" packet even though no IPsec rules are defined.
- Some IP addresses are being mistakenly interpreted as multicast addresses by the IPsec/Firewall feature.

Analog Fax:

- Cannot create a fax speed dial within the Embedded Web Server when signed in as a Device User even though the Access Control menu has given permission to the Device User accounts.
- Fax logs are not clearing properly when using a Web JetAdmin template to delete the fax activity log.
- Fax send jobs are stuck in the active jobs queue with some failing with communication error 200.
- 'Internal fax' is misspelled as 'Internet fax' when using the Japanese control panel language.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20190614
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2408067_049156
Embedded JetDirect	JSI24080014
CPB - Copy Processor Board	3.403
SCB - Scan Control Board	xxxxFA1921BR 1.0
Stapler/Stacker Finisher	LFP1N0051924B00
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.8
MD5 checksum for .bdl file	a653adcdf4f1bbc6766a85b74c89a122

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20190420

Firmware Revision: 2407166_000464

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.7.1.3

ENHANCEMENT:

Base:

- No New Updates

Digital Sending:

- No New Updates

Analog Fax:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

FIXES:

Base:

- "Remove Packaging Material" message will display on the control panel and the event log will show a 66.B5.12 Exhaust Fan 1 Stall error.
- "Paper Jam in the left door" message will display on the control panel and the event log will show a 66.B5.12 Exhaust Fan 1 Stall error.

Digital Sending:

- No New Updates

Analog Fax:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20190420
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2407166_000464
Embedded JetDirect	JSI24070104
CPB - Copy Processor Board	3.395
SCB - Scan Control Board	xxxxFA1848BR 1.0
Stapler/Stacker Finisher	LFP1N0051902A00
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.7.1.3
MD5 checksum for .bdl file	d4185d9c7b85984d3757d21bda0c74b5

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20190212

Firmware Revision: 2407163_000240

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.7.1

ENHANCEMENT:

Base:

- Added the UPC/A Font
- Added the ability to see scanning status on the Control Panel while performing a scan job.
- Italian language support added for the HP Accessibility Assistance.

- Slow or delayed first page printing from a Macintosh may occur due to the Security settings changing for default snmp to be "read only".

Digital Sending:

- No New Updates

Analog Fax:

- No New Updates

Security/Authentication:

- New security check will prevent installation of non-compliant aftermarket solution bundles. Currently installed solutions are unaffected. Please work with solution providers for an updated signature-compliant version of their software.

Embedded JetDirect:

- No New Updates

FIXES:

Base:

- Pull printing may fail due to an invalid SNMP status when the staple cartridge is missing or in a very low status.
- A 49.DE.05 Webkit encountered a fatal error, unable to recover error message may be observed when performing functions on the control panel with a pull-print solution installed.
- After a tray runs out of media the printer will prompt to load tray 1 even if another tray has similar media loaded.
- SafeNet AT SC650 v4.1 DoD SmartCard is not recognized.
- Embedded Web Server may hang with certain solutions installed when the Embedded Web Server is set to the Norwegian language.
- WS-Discovery packet causes 81.09.00 error.
- The "Use Requested Tray" setting within the Manage Trays section of the Embedded Web Page will temporarily change visually when setting tray size or type.
- A 49.4A.04 error may be seen intermittently when printing certain PDF files continuously for longer durations.

Digital Sending:

- Intermittently some pages are missing when performing Scan to Folder using 300 dpi and enabling High compression mode.
- An Operation Failed message is seen when typing in the email "to" field on devices managed by DSS.

Analog Fax:

- No New Updates

Security/Authentication:

- An invalid 33.05.21 Security Alert error occurs when waking device from sleep mode by opening the automatic document feeder.
- There is no prompt for PIN when accessing a function protected by Access Control with a DoD SmartCard installed.

Embedded JetDirect:

- No New Updates

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20190212
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2407163_000240
Embedded JetDirect	JSI24070104
CPB - Copy Processor Board	3.395
SCB - Scan Control Board	xxxxFA1848BR 1.0
Stapler/Stacker Finisher	LFP1N0051902A00
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.7.1
MD5 checksum for .bdl file	2d6f6f2aa15de504dcf430ac9245a6b1

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20181201

Firmware Revision: 2407071_037965

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.7

ENHANCEMENT:

Base:

- Added the ability to cancel all pending jobs at once. An access control setting "Details or Cancel any User's job" allows this to be restricted to logged-in users or administrators only.
- The checkbox "Show Preferred Domain Servers" has been added to the Windows Sign in Setup and Scan to Network Folder pages to allow the administrator to prioritize the order in which domain servers are tried.
- Added performance modification that reduces time to authenticate with a badge swipe.
- Added the ability to select the "General Office" print quality for Copy Jobs. This option can be configured via the Embedded Web Server and Control Panel.
- The Network Time Protocol server setting within the Embedded Web Server will no longer get auto deleted when the server cannot be reached after a few days.
- Added Job ID in Copy Archive meta data.
- Solution whitelisting has been enabled. Supported solutions include HP ROAM, HP Access Control, Safecom, Papercut and iSecStar.

Digital Sending:

- Added the ability to perform a Book Scan Mode for Digital Sending which is similar to the copy feature already present.
- Added the ability to perform 2-sided ID scans from within the Scan Mode menu for Embedded Digital Sending.

Analog Fax:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

FIXES:

Base:

- Barcodes generated with Code 128 font are not readable in certain conditions.
- A 49.38.0C error may occur when the printer is in a "Paper Out" condition and an IPDS print job is received.
- The "Evaluating Cartridge Level" message continues to show on the control panel even after the cartridge level check has completed.
- The Home button will not return the control panel to the proper Home Screen unless the Reset button is pressed when using an aftermarket solution.
- The Date and Time may be incorrectly formatted when the localization functions of the JavaScript Date object are used.
- Fax Archive fails if the Job Statistics and Local Quota service are enabled.
- An incorrect load prompt may be seen in certain conditions when OCR scanning a document and then printing the same scanned document.
- Storing a Person Job within the drivers Job Storage feature may take more time then compared to a FutureSmart 3 device.
- Some SmartCard solutions may fail to communicate with the card reader properly causing the authentication dialog window to not appear.
- The device may hang and not print when using and IPDS solutions installed for printing from an IBM Host system.
- A 49 error is seen when upgrading firmware from FutureSmart 3 to FutureSmart 4 when keyboard layout is set to Portuguese ABNT2.
- A duplex scan with job reservation from a Network TWAN application will hang in the processing state and will not complete when no target is loaded in the ADF.
- A 49.38.11 may be seen on the control panel when printing emails with special characters.

Digital Sending:

- Unable to delete fax speed dials when the device is being managed by Digital Send Software.

Analog Fax:

- No New Updates

Security/Authentication:

- Authentication agent Sign-In performance may be slow when using an aftermarket solution.
- Under certain circumstances the SIPR/NIPR card reader would go offline and require power cycle.
- A 403 error may occur on the control panel or solution server when using a non-default administrator role with an aftermarket solution.

Embedded JetDirect:

- Manual configuration settings may not be reported properly on the network configuration page when the network is disconnected.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20181201
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2407071_037965
Embedded JetDirect	JSI24070006
CPB - Copy Processor Board	3.390
SCB - Scan Control Board	xxxxFA1837BR 1.0
Stapler/Stacker Finisher	LFP1N0051840H00
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.7
MD5 checksum for .bdl file	de0fa6968e9e0145100de5296e81e126

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20180830

Firmware Revision: 2406314_034195

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.6.4

ENHANCEMENT:

Base:

- Added support for the HP PageWide Managed Color P77940dn+ (Y3Z65A) model.
- Added a check box selection next to the file name in Print from Job Storage. End users can now select one or more files to include in a job.
- Added a job masking feature to the Print from Job Storage application which prevents jobs that are password or PIN protected from showing up on the print jobs list. The end user must first enter the password or PIN.
- Added the ability to Hide or Show the Help Menus on the front control panel.
- Added French and Spanish language support to the HP Accessibility Assistant.
- Improved the time it takes for the printer to boot to a Ready state from the powered off state. This change also reduced the amount of time it takes to get the first page out for a copy or print job just after turning on the device.

- Added the ability to perform the Rotate Offset function which allow the device to sort copy or print jobs without a finisher attached.

Digital Sending:

- Added the ability to retrieve a network folder path from the contacts application instead of having to type the path in each time for scan to network folder.
- Added support to resolve "CWE-693 Protection Mechanism Failure" by providing "Strict-Transport-Security", "Content-Security-Policy" and "X-Content-Type-Options" HTTP security header support.

Analog Fax:

- No New Updates

Security/Authentication:

- Added support to resolve "CWE-693 Protection Mechanism Failure" by providing "Strict-Transport-Security", "Content-Security-Policy" and "X-Content-Type-Options" HTTP security header support.

Embedded JetDirect:

- No New Updates

FIXES:

Base:

- While under the management of a Quota service, large print jobs may become unresponsive to a Cancel Job request.
- Within the Embedded Web Server (EWS), for the Job Statistics and Quota Settings configuration pages, some text/numeric strings are incorrectly translated for Simple Chinese language.
- A delay in printing may be seen after first power on when comparing the same activity with previous versions of firmware.
- A 48.A1.01 error can intermittently occur when connected to a critical-client job accounting solution because a job was not properly marked as acknowledged. HP recommends unsubscribing/re-subscribing the job accounting solution after installing this firmware to ensure all legacy un-acknowledged jobs have been properly marked in the system.
- Certain files may print slower after upgrading to FutureSmart Bundle Version 4.6.2 or 4.6.2.1.

- Unable to print multiple copies when using Personal Job with Encryption (with password) and the PostScript UPD drivers.
- Stored Jobs won't print the number of copies which were entered if the "Done" button is not pressed first.
- Certain PDF's which contain masks with 1 bit per color components and have been created from scanned image may print slowly.
- A black line may appear when performing a 2-sided ID Copy from the Scan Mode Menu.

Digital Sending:

- Importing fax speed dials have missing entries for the Japanese region.

Analog Fax:

- Automatic population of group fax number when a single number is selected or entered.
- Fax confirmation prints the company name mirrored for Hebrew and other Right to Left languages.

Security/Authentication:

- A badge reader solution may become non-functional when swiping a badge during an error condition.
- Under certain circumstances the SIPR/NIPR card reader would go offline and require power cycle.

Embedded JetDirect:

- Some solutions may take longer to retrieve list of jobs by enabling Session caching for the IP address in addition to host name-based caching.
- Association/authentication problems with Jetdirect 2900nw and a wireless network when 802.11r fast roaming is enabled.
- An HTTP error 400 "Bad Request" may be seen when user tries to configure the Jetdirect 2700w in the Embedded Web Server.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20180830
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2406314_034195
Embedded JetDirect	JSI24060402
CPB - Copy Processor Board	3.388
SCB - Scan Control Board	xxxxFA1833AR 1.0

Stapler/Stacker Finisher	LCP1N0011830H00
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.6.4
MD5 checksum for .bdl file	57b67a8b5297fdd43b29e43f1b7ec1e9

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20180627

Firmware Revision: 2406206_031867

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.6.2

ENHANCEMENT:

Base:

- Adds an option in EWS to remove the job cancel button (red X) on the control panel.
- Added an option where Remote control panel screen can now be suppressed at the control panel.
- Added ability to allow users to cancel A3 jobs on A4 printers, mainly targeted for Pull printing customers.
- Added Import/Export feature from the control panel to USB drive of Address Book, Device User List, Quick Sets, and Home Screen Customization.
- Added the capability to create and enforce Local Quota for Server-Less Job Accounting that allow/limit/deny usage based on User Access Code .
- Added ability wherein when Local Quota is enabled, non-authenticated users, "guest" or "other" accounts will not be allowed to print, copy, or scan by default. The defaults for these non-authenticated users is Action=Stop and all quota credits=0 for prints, copies, and scans.
- Added the ability to reset Job Statistics from the Control Panel and print the Job Statistics report from the Control Panel and EWS (/w Admin Credentials) for Server-less Job Accounting.

Digital Sending:

- Adds job build functionality (non-image preview) for scan jobs.
- Enhancements to offline Address Book and Device User list editing and import.
- Added "Image Shift" feature to Copy and Scan to USB.
- Added support for Network Folder path in Contacts and allow users to save a Network Folder path in an individual contact record.

Analog Fax:

- Added ability to send long page faxes up to 28 inches.
- Added the ability to click on a speed dial entry to directly apply the fax number to the dialing list which will eliminate extra steps needed to complete the task.

Security/Authentication:

- Adds the ability to use an IP address in the IPPS configuration with HTTPS
- Added "Enable PS privileged operators" setting in the EWS Security/General Tab. When disabled (the default) the PostScript administrative passwords "SystemParamsPassword" and "StartJobPassword" are disabled and cannot be set. Any PS operator requiring these administrative passwords will not execute and return an error. When enabled both passwords default to "0" (zero) and can be set separately to an alphanumeric value.

Embedded JetDirect:

- Added a feature that allows configuring the complexity for SNMPv3 passphrase Authentication and privacy protocols

FIXES:

Base:

- The configurable default setting for a copy job destination will not retain after a power cycle.
- 49.38.07 errors may be seen when receiving faxes
- Error seen while enabling ePrint when device is set to "Norwegian" language.
- Certain barcode doesn't print correctly when using Direct PDF print.
- You may see a Data Received Warning and a very long pause between jobs when trying to send direct PDF file over a USB connection.
- After setting the Time format to a 24 Hour Clock you will see the format change back to a 12 Hour clock after a power cycle.
- "USB hubs cannot be attached in series. Remove extra hubs" message may be seen intermittently on the control panel.
- 63.4D.01 or 63.4D.02 error may be seen when coming out of deep sleep mode and a warning already exists on the control panel.
- "Edge-to-Edge" configuration is listed under Copy Settings on Current Settings Page, and within embedded Help menu on device, even though the device does not support the "Edge-to-Edge" feature.

- Changing "Use Requested Tray" will not stick if Access control menu "Ability to modify tray size and type settings" is locked even when signed in as Administrator.
- When quickly using the remote control panel provided in the Embedded Web Server an administrator may see keyboard characters dropping or characters being presented out of order on the actual control panel screen.
- Enabling or Disabling the Restrict Color feature within the Embedded Web Server will not work if there is a leading or trailing space in the application name coming from the PJI Jobacct info in the driver.
- When "PJI Drive Access" Setting is enabled/disabled via WJA, the setting is not retained after a power cycle.

Digital Sending:

- 49.38.07 error is seen under some conditions when the user was typing an email address into the scan-to-email TO: field.
- 44.01.3F events are seen in event log when performing scan to email with LDAP.
- 49.DE.11 error may be seen during LDAP search in certain conditions.

Analog Fax:

- No New Updates

Security/Authentication:

- When the Device Guest does not have the Print in Color permission in Access Control and users cannot select Alternate Sign In Methods, jobs sent to the device using the HP Universal Printer Driver will print in color again.
- A user's domain account may get locked out prematurely when attempting to log in at the printer due to entering an incorrect Windows domain credential.
- Card swipes may be lost or delayed when initiating an authentication session.
- CVE-2015-9251: jQuery before version 1.12.0 and 3.0.0 may be vulnerable to Cross-site Scripting (XSS) attacks.
- EWS>Security>Access Control default sign-in method for the HP AC Secure Pull Print button is reset to "Local Device" from "HPAC - DRA Server" following a firmware upgrade.
- CVE-2018-5923 - Solution application signature checking may allow potential execution of arbitrary code.

Embedded JetDirect:

- No longer possible for the device to lose network connection after re-negotiating the link speed.
- Jetdirect 3000w not recognized by products localized for Japan.

- Device might exhibit a 81.09.00 error associated with certain HP AC authentication use cases involving multiple servers behind a network load balancer.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20180627
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2406206_031867
Embedded JetDirect	JSI24060206
CPB - Copy Processor Board	3.385
SCB - Scan Control Board	xxxxFA1825AR 1.0
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.6.2
MD5 checksum for .bdl file	007788426f3bf381ab55415ac3d3cce1

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20180621

Firmware Revision: 2406086_000011

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.6.0.3

ENHANCEMENT:

Base:

- No New Updates

Digital Sending:

- No New Updates

Analog Fax:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

FIXES:

Base:

- Copy or Scanned images from the flatbed glass may be rotated and clipped. – (Continued improvements)

Digital Sending:

- No New Updates

Analog Fax:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20180621
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2406086_000011
Embedded JetDirect	JSI24060004
CPB - Copy Processor Board	3.385
SCB - Scan Control Board	xxxxFA1825AR 1.0
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.6.0.3
MD5 checksum for .bdl file	3aa296aab0002ca2946995b9f8c6a9b8

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20180612

Firmware Revision: 2406084_000007

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.6.0.2

ENHANCEMENT:

Base:

- No New Updates

Digital Sending:

- No New Updates

Analog Fax:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

FIXES:

Base:

- Copy or Scanned images from the flatbed glass may be rotated and clipped when scanner is in direct sunlight.

Digital Sending:

- No New Updates

Analog Fax:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20180612
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2406084_000007
Embedded JetDirect	JSI24060004
CPB - Copy Processor Board	3.384
SCB - Scan Control Board	xxxxFA1823BR 1.0
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.6.0.2
MD5 checksum for .bdl file	8643ac3160f894a6aac02e4f801ef3b8

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20180510

Firmware Revision: 2406048_029618

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.6.0.1

ENHANCEMENT:

Base:

- No New Updates

Digital Sending:

- No New Updates

Analog Fax:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

FIXES:

Base:

- Fixed a defect where it would prevent a proximity card reader from properly communicating with the printer running solutions using OXPd 1.7-based authentication.
- Fixed a defect where it caused "Ok" and "Cancel" buttons to not be displayed for HP Access Control code authentication.

Digital Sending:

- No New Updates

Analog Fax:

- No New Updates

Security/Authentication:

- No New Updates

Embedded JetDirect:

- No New Updates

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Datecode: 20180510
HP PageWide Color MFP P779xx SERIES	Firmware Revision: 2406048_029618
Embedded JetDirect	JSI24060004
CPB - Copy Processor Board	3.379
SCB - Scan Control Board	xxxxFA1809AR 1.0
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.6.0.1
MD5 checksum for .bdl file	e28dfffceba966d7a7b2527e5d24d697

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Revision: 2406029_028982

Firmware Datecode: 20180425

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 4.6

ENHANCEMENT:

Base:

- No New Updates – Original Release

Digital Sending:

- No New Updates – Original Release

Analog Fax:

- No New Updates – Original Release

Security/Authentication:

- No New Updates – Original Release

Embedded JetDirect:

- No New Updates – Original Release

FIXES:

Base:

- No New Updates – Original Release

Digital Sending:

- No New Updates – Original Release

Analog Fax:

- No New Updates – Original Release

Security/Authentication:

- No New Updates – Original Release

Embedded JetDirect:

- No New Updates – Original Release

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP PageWide Color MFP P77440 SERIES	Firmware Revision: 2406029_028982
HP PageWide Color MFP P779xx SERIES	Firmware Datecode: 20180425
Embedded JetDirect	JSI24060004
CPB - Copy Processor Board	3.379
SCB - Scan Control Board	xxxxFA1809AR 1.0
Fax	Ver11.4A
HP Fleet Release Designation	Original Release FutureSmart 4.6
MD5 checksum for .bdl file	

No Previous Releases – Original Version

Installation Instructions

NOTE: Please be aware that an update in some circumstances may require 10 minutes or more to complete.

You can send the firmware update to a device at any time; the device will wait for all I/O channels to become idle before cycling power.

Please print a configuration page prior to performing any firmware update. To print the configuration page:

1. Go to the printer's control panel.
2. Swipe left and select the **Reports** menu.
3. Select the **Configuration/Status Pages** menu.
4. Select the **Configuration Page** option.
5. Select the **Print**.

On the printed Configuration page look in the section marked "Device Information" for the Firmware Datecode and Firmware Revision. The Firmware Datecode and Firmware Revision will look something like this:

Firmware Revision: 2406029_028982
Firmware Datecode: 20180425

The elapsed time for an update depends on the I/O transfer time as well as the time that it takes for the printer to reinitialize. The I/O transfer time depend on the speed of the host computer sending the update and the I/O method (USB or network).

The re-initialization time will depend on the specific hardware configuration of the printer, such as the number of EIO devices installed, the presence of external paper handling devices, and the amount of memory installed. Finally, any print jobs ahead of the firmware job in the queue will be printed before the update is processed.

NOTE: When the update process has completed the PageWide will need to be rebooted. Once the printer is back online, print a Configuration Page and verify that the new firmware has been installed.

Additional information to know

The firmware file will be in the following file format "xxxxxxx.bdl" where "xxx" indicates the firmware file name and the ".bdl" is the files extension.

This file requires an interactive update method. You cannot update the printer using the traditional FTP, LPR or Port 9100 methods of upgrading. Please use one of the following methods listed below to update the firmware of this device.

How to perform firmware upgrades.

Embedded Web Server: (control panel is at a Ready screen)

After uncompressing the file you will see a xxxxxxxx.bdl file.

1. Open an Internet Browser Window.
2. Enter the IP address in the URL line.
3. Select the **Firmware Upgrade** link from within the General tab.
4. Select **Choose File** and browse to the location that the firmware upgrade file was downloaded to, and then select the firmware file.
5. Select the **Install** button to perform the upgrade.

NOTE: Do not close the Browser Window or interrupt communication until the Embedded Web Server displays the Confirmation Page.

6. The printer will automatically reboot unless you are downgrading. If downgrading Firmware you will be prompted to select the Rollback option.

NOTE: Please be aware that an update in some circumstances may require 10 minutes or more to complete.

Once the printer or MFP is back online, print a Configuration Page and verify that the new firmware has been installed.

Walk-up USB thumb drive: (Standard control panel menu)

After uncompressing the file you will see a xxxxxxxx.bdl file.

1. Copy the xxxxxxxx.bdl file to a portable USB flash memory storage device (thumb drive).

NOTE: USB Flash Drives that are not in a Fat32 format or having a CD formatted partition may not be recognized by the printer. You may need to try a different USB flash drive.

2. Turn the printer ON.
3. Swipe to the left and select the **Support Tools** application.
4. Select the **Maintenance** menu
5. Select the **USB Firmware Upgrade** menu.
6. Insert the portable USB storage device with the xxxxxxxx.bdl file on it into the USB port on the front control panel of the product.
7. Select the xxxxxxxx.bdl file you would like to use.

NOTE: If there is more than one xxxxxxxx.bdl file on the storage device, make sure that you select the correct file for this product.

8. Select the **Install** button on the bottom of the screen.

9. Select the **Upgrade, Re-install or Downgrade** option depending on the task you are performing. The firmware upload process will begin.

When the upload is complete, the printer will reboot automatically and start the upgrade process.

NOTE: The upgrade process may take up to 10 minutes to complete. Please do not interrupt the updating process.

Once the printer or MFP is back online, print a Configuration Page and verify that the new firmware has been installed.

Pre-Boot walk-up USB thumb drive: (control panel Pre-Boot menu)

NOTE: Only to be used if the printer is not able to boot to READY

After uncompressing the file you will see a xxxxxxx.bdl file.

1. Copy the xxxxxxx.bdl file to a portable USB flash memory storage device (thumb drive).

NOTE: USB Flash Drives that are not in a Fat32 format or having a CD formatted partition may not be recognized by the printer. You may need to try a different USB flash drive.

2. Turn the printer ON.
3. Press the **HP** logo in the middle of the screen when you see the "**1/8**" under the logo.
4. Press the Down arrow to highlight **Administrator**, and then press OK.
5. Press the Down arrow to highlight **Download**, and then press OK.
6. Insert the portable USB storage device with the xxxxxxx.bdl file on it.
7. Press the Down arrow to highlight **USB Thumbdrive**, and then press OK.
8. Press the Down arrow to highlight the xxxxxxx.bdl file, and then press OK.

NOTE: Please make sure the firmware file is located in the root directory of the flash drive. If you have more than one .bdl file on your USB flash drive, select the file you want loaded and press OK.

Please be patient since this may take up to 10 minutes to complete.

9. When the message **Complete** appears on the control panel display, power cycle the printer.
10. The printer will start the upgrade process and will continue to boot to the Ready state.

NOTE: Please be patient since this may take up to 10 minutes to complete.

Once the printer or MFP is back online, print a Configuration Page and verify that the new firmware has been installed.

Web Jetadmin (Supported with version 10.4 SR1 with FP4 or newer)

Please visit www.hp.com and type "Web Jet Admin" in the "Search" Box to find more information about new releases of Web Jetadmin and the release note information for those releases.

Upgrading Firmware:

1. Start Web Jetadmin 10.4 SR1 with FP4 or newer
2. From the "Device Management" section, select "All Devices" (or the appropriate device group). An "All Devices" list will appear in the center window.
3. Find your device in the list, or type the IP address of the device in the Quick Device Discovery section in the lower-left of the screen (this will highlight your device in the device list). You can sort the device list by clicking on a column name at the top.
4. If your device list is sorted by model number, you may select multiple devices with the same model number by Control-Click or Shift-Click.
5. Right-click on the device and select "Upgrade firmware...".
6. An Upgrade Firmware window will appear. Select "Device firmware" and click "Next"
7. A list of available firmware will appear. If the correct version is listed, click "Next", and the upgrade process will start.

NOTE: If the correct firmware version does not appear within the list, you will need to manually upload it into WJA. New firmware may be available on an FTP site prior to appearing on hp.com. The instructions below allow you to upload a firmware file from your local PC to WJA 10.4 SR1 with FP4 or newer

Uploading new firmware files into WJA:

1. Click on "Firmware/Firmware Repository" in the "Device Management" pane
2. A "Firmware Repository" window will appear in the center of the screen
3. Click on "Upload" in the upper-right of the window
4. Browse to the .bdl file on your local PC
5. Click "Upload"
6. Once the .bdl file is uploaded, go back to step 2 in the first section and complete steps 2 through 6.

NOTE: Do not turn printer off during the update process! When the update process is complete, the printer will automatically reboot. If the firmware update process fails, Web

JetAdmin will provide notification with a page (screen) of information regarding the reason(s) for failure. A link will be provided to attempt the process again.

System Requirements

The Firmware upgrade process requires a network or USB port connection.

Technical Assistance

Some of the services below are provided for the United States only. Similar services to those listed below are available in other countries. See your printer's user guide or call your local authorized HP dealer.

Customer Support

See your printer's user guide or call your local authorized HP dealer.

Internet

An anonymous FTP library service is available worldwide for around-the-clock access to drivers and technical support information for HP peripheral and computer products.

Please note that paths may change without notice. Access the Internet or FTP address and use the menus to locate the software or support of your choice.

URL for HP PageWide Color MFP P77440 and P779xx series Support:

URL for Firmware downloads:

www.hp.com/support/pwP77440mfp

www.hp.com/support/pwP77940mfp

www.hp.com/support/pwP77950mfp

www.hp.com/support/pwP77960mfp

URL for Support:

<http://www.hp.com/go/support>

URL for Access HP: <http://www.hp.com>

FTP address: <ftp.hp.com>

Login: anonymous

Password: your Internet email address

Additional Information

Refer to your printer's user guide for additional methods of obtaining software and support information, such as printer driver distribution centers other online services, fax services, and other online support.

Legal Statements

Trademark Notices

MS-DOS, Windows, Windows 2000, Excel 2000, Microsoft Office, Windows Server 2003, Outlook, PScript and Internet Explorer are registered trademarks of Microsoft Corporation in the United States and/or other countries.

PostScript is a registered trademark of Adobe Systems Incorporated.

Quark and QuarkXpress are trademarks of Quark Inc.

Mac, Macintosh and Safari are registered trademarks of Apple Computer, Inc.

The Adobe logo, Acrobat, the Adobe PDF logo, Distiller, and Reader are either registered trademarks or trademarks of Adobe Systems Incorporated in the United States and/or other countries.

Novell is a registered trademark of Novell, Inc., in the United States and other countries.

Netscape Navigator, is a registered trademark of Netscape Communications Corporation in the United States and other countries.

License and Copyright

© Copyright 2018 HP Inc., L.P.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein