

AOS-CX 10.12.1020 Release Notes

6200 Switch Series



a Hewlett Packard
Enterprise company

Copyright Information

© Copyright 2023 Hewlett Packard Enterprise Development LP.

This product includes code licensed under certain open source licenses which require source compliance. The corresponding source for these components is available upon request. This offer is valid to anyone in receipt of this information and shall expire three years following the date of the final distribution of this product version by Hewlett Packard Enterprise Company. To obtain such source code, please check if the code is available in the HPE Software Center at <https://myenterpriselicense.hpe.com/cwp-ui/software> but, if not, send a written request for specific software version and product for which you want the open source code. Along with the request, please send a check or money order in the amount of US \$10.00 to:

Hewlett Packard Enterprise Company
Attn: General Counsel
WW Corporate Headquarters
1701 E Mossy Oaks Rd Spring, TX 77389
United States of America.

Notices

The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from Hewlett Packard Enterprise required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Links to third-party websites take you outside the Hewlett Packard Enterprise website. Hewlett Packard Enterprise has no control over and is not responsible for information outside the Hewlett Packard Enterprise website.

Acknowledgments

Microsoft and Windows are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

Products Supported

This release applies to the 6200 Switch Series. The following table lists any applicable minimum software versions required for that model of switch.



If your product is not listed in the below table, no minimum software version is required.

Product number	Product name	Minimum software version
JL724A	Aruba 6200F 24G 4SFP+ Switch	10.04.1000
JL725A	Aruba 6200F 24G Class4 PoE 4SFP+ 370W Switch	10.04.1000
JL726A	Aruba 6200F 48G 4SFP+ Switch	10.04.1000
JL727A	Aruba 6200F 48G Class4 PoE 4SFP+ 370W Switch	10.04.1000
JL728A	Aruba 6200F 48G Class4 PoE 4SFP+ 740W Switch	10.04.1000
R8V08A	Aruba 6200M 24G 4SFP+ TAA Switch	10.11.1005
R8V09A	Aruba 6200M 24G Class4 PoE 4SFP+ TAA Switch	10.11.1005
R8V10A	Aruba 6200M 48G 4SFP+ TAA Switch	10.11.1005
R8V11A	Aruba 6200M 48G Class4 PoE 4SFP+ TAA Switch	10.11.1005
R8V12A	Aruba 6200M 36G 12SR5 Class6 PoE 4SFP+ TAA Switch	10.11.1005
R8V13A	Aruba 6200F 12G Class4 PoE 2G/2SFP+ 139W TAA Switch	10.11.1005
R8Q72A	Aruba 6200F 12G Class4 PoE 2G/2SFP+ 139W Switch	10.11.1005
R8Q67A	Aruba 6200M 24G 4SFP+ Switch	10.11.1005
R8Q68A	Aruba 6200M 24G Class4 PoE 4SFP+ Switch	10.11.1005
R8Q69A	Aruba 6200M 48G 4SFP+ Switch	10.11.1005
R8Q70A	Aruba 6200M 48G Class4 PoE 4SFP+ Switch	10.11.1005
R8Q71A	Aruba 6200M 36G 12SR5 Class6 PoE 4SFP+ Switch	10.11.1005
JL724B	Aruba 6200F 24G 4SFP+ Switch	10.13.0001

Product number	Product name	Minimum software version
JL725B	Aruba 6200F 24G Class 4 PoE 4SFP+ 370W Switch	10.13.0001
JL726B	Aruba 6200F 48G 4SFP+ Switch	10.13.0001
JL727B	Aruba 6200F 48G Class 4 PoE 4SFP+ 370W Switch	10.13.0001
JL728B	Aruba 6200F 48G Class 4 PoE 4SFP+ 740W Switch	10.13.0001
S0M81A	Aruba 6200F 24G 4SFP Switch	10.13.0001
S0M82A	Aruba 6200F 24G Class 4 PoE 4SFP 370W Switch	10.13.0001
S0M83A	Aruba 6200F 48G 4SFP Switch	10.13.0001
S0M84A	Aruba 6200F 48G Class 4 PoE 4SFP 370W Switch	10.13.0001
S0M85A	Aruba 6200F 48G Class 4 PoE 4SFP 740W Switch	10.13.0001
S0M86A	Aruba 6200F 24G 4SFP+ TAA-compliant Switch	10.13.0001
S0M87A	Aruba 6200F 24G Class 4 PoE 4SFP+ 370W TAA-compliant Switch	10.13.0001
S0M88A	Aruba 6200F 48G 4SFP+ TAA-compliant Switch	10.13.0001
S0M89A	Aruba 6200F 48G Class 4 PoE 4SFP+ 370W TAA-compliant Switch	10.13.0001
S0M90A	Aruba 6200F 48G Class 4 PoE 4SFP+ 740W TAA-compliant Switch	10.13.0001
S0G13A	HPE Aruba Networking CX 6200F 24G 4SFP TAA-compliant Switch	10.13.0001
S0G14A	HPE Aruba Networking CX 6200F 24G Class 4 PoE 4SFP 370W TAA-compliant Switch	10.13.0001
S0G15A	HPE Aruba Networking CX 6200F 48G 4SFP TAA-compliant Switch	10.13.0001
S0G16A	HPE Aruba Networking CX 6200F 48G Class 4 PoE 4SFP 370W TAA-compliant Switch	10.13.0001
S0G17A	HPE Aruba Networking CX 6200F 48G Class 4 PoE 4SFP 740W TAA-compliant Switch	10.13.0001

Important information for 6200 Switches



Aruba switches covered by this release note use eMMC or SSD storage. This is non-volatile memory for persistent storage of config, files, databases, scripts, and so forth. Aruba recommends updating to version 10.06.0100 or later (including this release) to implement significant improvements to memory usage and prolong the life of the switch.



Starting from AOS-CX 10.12.1010, switches will only support TLSv1.2 ciphers and curves approved by the NIAP on all supported applications such as Secure RADIUS (RadSec), Captive Portal, and EAP-TLS clients. It is advised to upgrade your Secure RADIUS server to a version that supports the NIAP approved ciphers and curves and disable the unsupported ciphers from your EAP-TLS clients. NIAP approved ciphers and curves are DHE-RSA-AES128-GCM-SHA256, DHE-RSA-AES256-GCM-SHA384, ECDHE-ECDSA-AES128-GCM-SHA256, ECDHE-ECDSA-AES256-GCM-SHA384, ECDHE-RSA-AES128-GCM-SHA256, ECDHE-RSA-AES256-GCM-SHA384, secp521r1, secp384r1, and prime256v1.

To avoid damage to your equipment, do not interrupt power to the switch during a software update.



Clear the browser cache after upgrading to this version of software before logging into the switch using a Web UI session. This will ensure the Web UI session downloads the latest changes.



Switch fans will run at full speed when a fault is detected with the temperature sensors in the switch. This is normal behavior to ensure overheating does not occur. Should the fans run at full speed at unexpected times, check the output of `show environment temperature` and `show environment fans`, then contact support for further assistance.

If a switch has RPSVST enabled and the native VLAN ID configured for a trunk interface is not the default VLAN ID 1, and the native VLAN ID is also used as the management VLAN, the switch may not be accessible over the trunk interface after upgrading from any 10.04.00xx version of software.

To fix the issue after an upgrade, log into the switch using the OOBM interface or serial port console and configure the following:



```
switch# configure
switch(config)# spanning-tree rpsvst-mstp-interconnect-vlan <VLAN_ID>
```

where <VLAN_ID> is the native VLAN ID configured on the trunk interface.

If there are multiple trunk interfaces configured on the switch, each with a different VLAN ID, contact the Aruba Support Team.



If the switch has the always-on PoE feature enabled, during the upgrade from a version of software prior to 10.05.0001 to this version of software, PoE Powered Devices (PDs) will lose power from the switch as the switch will power cycle during the update. Plan a time for upgrading the switch when loss of power to the PDs attached to the switch can be mitigated.

To restore a previous configuration when downgrading to a previous version of software, follow these steps:

1. Use the `show checkpoint` command to see the saved checkpoints and ensure that you have a checkpoint that is an exact match of the target software version (see the `Image Version` column in the output of the command, for example ML.10.0x.yyyy).

This checkpoint can be the startup-config-backup automatically created during the initial upgrade or any other manually created checkpoint for the target software version.

2. Copy the backup checkpoint into the startup-config.
 3. Boot the switch to the target version (lower version), making sure to select `no` when prompted to save the current configuration.
-



To use ROP interfaces, an internal VLAN range must be defined. See the `system internal-vlan-range` command located in the *Layer 2 Bridging Guide* for more information.



For information about Short Supported Releases (SSRs) and Long Supported Releases (LSRs), see <https://www.arubanetworks.com/support-services/end-of-life/arubaos-software-release/>.

To upgrade to:	Your switch must be running this version or later:
AOS-CX 10.12.xxxx Note: 10.12 is an SSR, recommended release is 10.12.0006	AOS-CX 10.09.0002
AOS-CX 10.11.xxxx Note: 10.11 is an SSR, recommended release is 10.11.0001	AOS-CX 10.08.0001
AOS-CX 10.10.xxxx Note: 10.10 is an LSR, recommended release is 10.10.10xx.	AOS-CX 10.06.0110
AOS-CX 10.09.xxxx Note: 10.09 is an SSR, recommended release is 10.09.10xx.	AOS-CX 10.06.0110
AOS-CX 10.08.xxxx Note: 10.08 is an SSR, recommended release is 10.09.10xx.	AOS-CX 10.05.0001
AOS-CX 10.07.xxxx Note: 10.07 is an SSR, recommended release is 10.09.10xx.	AOS-CX 10.04.0001

Refer to the Approved Product Lists sites for the Common Criteria, FIPS 140-2 and DoDIN APL to obtain the product certification details. Products should be used as evaluated and defined in the respective configuration guides.

- Common Criteria: <https://www.niap-ccevs.org/Product/>
- FIPS 140-2: <https://csrc.nist.gov/Projects/Cryptographic-Module-Validation-Program/Validated->

[Modules/Search](#)

- DoDIN APL: <https://aplots.disa.mil/processAPList.action>

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open-source licenses. A complete machine-readable copy of the source code corresponding to such code is available upon request. This offer is valid to anyone in receipt of this information and shall expire three years following the date of the final distribution of this product version by Hewlett Packard Enterprise Company. To obtain such source code, send a check or money order in the amount of US \$10.00 to:

Hewlett Packard Enterprise Company
Attn: General Counsel
6280 America Center Drive
San Jose, CA 95002
U.S.A.

Please specify the product and version for which you are requesting source code. You may also request a copy of this source code free of charge at: <https://hpe.com/software/opensource>

Version history

All released versions are fully supported by Aruba, unless noted in the table.

Version number	Release date	Remarks
10.12.1020	12-12-2023	Released, fully supported, and posted on the Web.
10.12.1010	05-10-2023	Released, fully supported, and posted on the Web.
10.12.1000	02-08-2023	Released, fully supported, and posted on the Web.
10.12.0006	31-05-2023	Released, fully supported, and posted on the Web.

Compatibility/interoperability

The switch web agent supports the following web browsers:

Browser	Minimum supported versions
Edge (Windows)	41
Chrome (Ubuntu)	76 (desktop)
Firefox (Ubuntu)	56
Safari (MacOS)	12
Safari (iOS)	10 (Version 12 is not supported)



Internet Explorer is not supported.

Recommended versions of network management software for switches found in this release note:

Management software	Recommended version(s)
NetEdit	2.8.0
Aruba Central	2.5.7
Central On-Premises	2.5.6.4
Aruba CX Mobile App	Support coming in future release.
IMC	(708P03)



For more information, see the respective software manuals.



To upgrade software using NetEdit, make sure to upgrade to the above version of NetEdit first and then execute the switch software upgrade on devices discovered by this version of NetEdit.

Enhancements

This section describes the enhancements introduced in this release.

Category	Description
PKI	<p>In previous releases, under a certificate configuration context, the key-size or curve-size is a mandatory keyword following a key-type, even when the key-size to configure is the default value. For example:</p> <pre>(config-cert01)# key-type rsa key-size 2048 (config-cert01)# key-type ecdsa curve-size 256</pre> <p>Starting with AOS-CX 10.12.1020, when the key-curve-size to configure is the default value, the key-size/curve-size keyword is optional and may be omitted. For example, this command</p> <pre>(config-cert01)# key-type ecdsa</pre> <p>Is equivalent to:</p> <pre>(config-cert01)# key-type ecdsa curve-size 256</pre> <p>And this command:</p>

Category	Description
	<pre>(config-cert01)# key-type rsa</pre> <p>Is equivalent to:</p> <pre>(config-cert01)# key-type rsa key-size 2048</pre>

Resolved Issues

This section lists fixes found in this branch of the software. The **Symptom** statement describes what a user might experience if this issue is seen on the network. The **Scenario** statement provides additional environment details and trigger summaries. When available, the **Workaround** statement provides a workaround to the issue for customers who chooses not to update to this version of software.

For a list of issues resolved in the previous releases of 6200 switches, refer to the [AOS-CX Release Notes Portal](#).



The Bug ID is used for tracking purposes.

Resolved issues

This section describes the issues resolved in this release.

Category	Bug ID	Description
PKI	283686	<p>Symptom: When an X509 certificate profile configuration with an EST profile association is pushed to a switch, it can trigger the EST enrollment two times, causing the EST server to issue two certificates to the switch.</p> <p>Scenario: This issue has no functional impact, because only the latest enrolled certificate will take effect.</p>
ASIC SDK -HPE	277504	<p>Symptom: A VSF stack breaks apart and a stack member reboots.</p> <p>Scenario: This occurs if an invalid client is connected to a downlink or if a counterfeit transceiver is connected to the uplink.</p> <p>Workaround: Disable the problematic ports and reboot the switch.</p>
WebUI	279019	<p>Symptom: After uploading an invalid PER certificate, the hpe-restd process becomes unstable, the WebUI temporarily stops responding, and all REST API calls from the WebUI fail.</p> <p>Scenario: If a user uploads a corrupt PEM certificate file using WebUI certificate management window, selecting the Upload button in the WebUI causes the WebUI to stop working completely. To recover from this state, restart hpe-restd from the bash prompt in the command-line interface or restart the switch.</p> <p>Workaround: Use the CLI to upload certificates.</p>
Central	279046	<p>Symptom: A firmware upgrade from Aruba Central will fail.</p> <p>Scenario: This issue occurs when switch's connection to the internet is configured using the command ip source-interface http or ip source-interface all.</p> <p>Workaround: Configure the switch to connect to the internet</p>

Category	Bug ID	Description
		without using an ip source interface.
WebUI	282016	<p>(For 6300 Switch Series only)</p> <p>Symptom: The Interface Edit button on WebUI PoE interface page is disabled when the selected PoE interface's power enable status setting is disabled.</p> <p>Scenario: This issue occurs when a user accesses the WebUI's PoE Interface page on a PoE switch, edits the PoE configuration of an interface/port, sets the Power Enable option to disabled, then saves these settings. After this, the Edit button for this interface/port on WebUI will not be enabled to reconfigure this interface/port for any other PoE configuration.</p> <p>Workaround: Edit the PoE configuration of Interface/Port from the command-line interface or re-enable the Power Enable option for the Interface/Port from the CLI to reenable the Edit button again in the WebUI.</p>
SNMP	281792	<p>Symptom: A desired source IP address is not seen when inform packets are received by the inform receiver.</p> <p>Scenario: This issue occurs when a user sets a source IP address for traps.</p>
RADsec	282524	<p>Symptom: Client authentication is not successful after a VSF conductor reboot.</p> <p>Scenario: This issue occurs when a VSF conductor is rebooted or when the port-accesssd daemon is restarted.</p> <p>Workaround: Reconfigure the RADIUS server.</p>
Device-Profile	284093	<p>Symptom: The port-accesssd daemon crashes and generates the following log file message:</p> <pre>LOG_EMERG CDTR 1 PORTACCESS PORTACCESS DEVICEPROFILE Received a NULL pointer in one or more function arguments.</pre> <p>Scenario: The issue is observed when a device connected to the switch advertises LLDP information with a TLV value greater than 256 Bytes.</p>
PKI	281380	<p>Symptom: When a certificate is validated, the event log did not indicate what CA certificate was used to validate the certificate. A new event is added to this release to provide the CA certificate information.</p> <p>Scenario: This issue occurs when validating an Aruba Central server certificate.</p>
PKI	262792	<p>Symptom: The hep text for the crypto pki certificate command had an additional special character) in the default value.</p> <p>Scenario: Enter the certificate context to configure a X509 certificate and then type shift+? to see the help text.</p>

Feature Caveats

The following are feature caveats that should be taken into consideration when using this version of the software.

Feature	Description
REST	The REST v1 API that was deprecated in previous release of AOS-CX is completely deactivated and no longer available in AOS-CX 10.12. For more information on migrating your deployment from the RESTv1API to the RESTv10.xx API, refer to the REST API Migration Quick Start Guide .
REST	<p>When a user configures a RADIUS server via REST with AOS-CX 10.11 or lower, the REST operation fails. A schema change introduced in the RADIUS_Server table in 10.12 is not backward compatible with REST versions 10.11 and lower. A checkpoint restore operation will fail on a switch running 10.12 firmware if the checkpoint is created on a 10.11 or lower release and includes RADIUS server configurations.</p> <p>Use REST version 10.12 to configure RADIUS servers on a switch running AOS-CX 10.12.xxxx. When using checkpoints with RADIUS server configurations, do not restore the checkpoint directly on a switch running 10.12 firmware. Instead,</p> <ol style="list-style-type: none"> 1. Copy the running-config from the switch running the 10.11 or lower release firmware to a remote server as CLI commands (and not as a JSON file). 2. Erase the startup-config on the switch. 3. Upgrade without saving the configuration to 10.12.xxxx. 4. Copy the running-config from the remote server, or apply the entire configuration from scratch on the switch running the 10.12 firmware.
SNMP	When SNMP is enabled via the switch CLI, it can take between 1-2 minutes for the SNMP daemon to be ready to respond to requests. If a local or external SNMP MIB walk is performed in the interval between when SNMP is first enabled and the SNMP daemon is ready, the MIB walk action will return an error.
Certificates	When a switch uses a certificate with a legacy certificate name that is not supported in 10.12 because it contains disallowed characters, the information will migrate properly in the upgrade, but that certificate can no longer be edited. For new certificate names, only alphanumeric characters, dots, dashes, and underscores are allowed.
ACLs	In a VSF stack, the switch may fail to log events for the matching access-list entries. ACL functionality is not impacted; access-list entries are applied properly and only the logging is incorrectly generated.
Aruba CX Mobile App	VSF stack formation is blocked when there are reserved autojoin interfaces (25, 26, 49, 50) in the stack topology.
Classifiers	For Classifier policy modifications to be secure, Aruba strongly encourages modifications be done as a three-step process: Bring down the port, modify, and bring the port back up.
Classifiers	Policies containing both MAC and IPv6 classes are not allowed.
CMF	Automatic downgrade of the startup-config is not supported during a software downgrade. To restore a configuration use the procedure documented in Manual configuration restore for software downgrade .
CMF	No other checkpoint besides "startup-configuration" gets migrated during the upgrade process.

Feature	Description
ICMP Redirect	The switch may only software forward at a rate of 100pps if the packets that trigger ICMP redirect.
MACsec	MACsec works between a CX device and a Windows VM running AnyConnect with AES-128 cipher. AnyConnect does not support AES-256 in the NAM module (works only for the VPN module).
MACsec	When Cisco AnyConnect is used as dot1x supplicant, it is recommended to configure cak-length to be 16 under dot1x-authenticator mode.
MACsec	Ensure the cipher suite GCM-AES-128 is configured when AOS-CX is acting as a key server. This is because, by default AOS-CX will use the most secure cipher suite gcm-aes-xpn-256 for establishing MACsec secure link and Comware/PVOS doesn't support an XPN cipher suite.
OSPF	OSPFv2 and OSPFv3 do not support detailed LSA show commands.
RADIUS	Authorization by means of HPE VSAs is not supported.
REST	REST supports the 'admin' and 'operator' roles but does not work with TACACS+ command authorization.
RIP/RIPng	RIP/RIPng metric configuration support is not available.

Known issues

The following are known open issues with this branch of the software. The **Symptom** statement describes what a user might experience if this is seen on the network. The **Scenario** statement provides additional environment details and trigger summaries. When available, the **Workaround** statement provides a workaround to the issue.

Category	Bug ID	Description
L3 Routes	207077	<p>Symptom: Traffic convergence takes approximately two minutes when VSF switchover is performed.</p> <p>Scenario: This issue occurs when traffic is flowing through the switch using the uplink on the conductor. Performing a VSF switchover causes the standby to become the new conductor, and it takes approximately 2 minutes for traffic to resume using the uplink of the new conductor.</p> <p>Workaround: If the Uplink from the VSF is a LAG with members in Conductor/Standby/Member, the convergence time would be lesser and around 70 seconds.</p>
Internal srvc: Security PA infra	275859	<p>Symptom: Port-Access security clients not onboarding after the following sequence of configuration change on a port.</p> <p>Scenario: This issue can occur if port-access security is enabled on port (802.1X/MAC-Auth/Port-Security/Device profile with security), and the configurations are cleared at port level using the default interface <interface-name> command on the port-access security enabled port. When port-access security is reenabled again at the same port level, port-access security clients will not be onboarded on the port.</p> <p>Workaround Recover from this issue by performing a port flap via the commands shut and no shut.</p> <p>Perform a port flap (shut/no shut) at the port level if the command default interface <interface-name> is issued on a port-access security enabled port, then reenables port-access security again on that port.</p>

Upgrade information

AOS-CX 10.12.0006 uses ServiceOS ML.01.12.0005.

If a switch has RPVST enabled and the native VLAN ID configured for a trunk interface is not the default VLAN ID 1, and the native VLAN ID is also used as the management VLAN, the switch may not be accessible over the trunk interface after upgrading from any 10.04.00xx version of software.

To fix the issue after an upgrade, log into the switch using the OOBM interface or serial port console and configure the following:



```
switch# configure
switch(config)# spanning-tree rpvst-mstp-interconnect-vlan <VLAN_ID>
```

where <VLAN_ID> is the native VLAN ID configured on the trunk interface.

If there are multiple trunk interfaces configured on the switch, each with a different VLAN ID, contact the Aruba Support Team.



Do not interrupt power to the switch during this important update.



Some Network Analytics Engine (NAE) scripts may not function properly after an upgrade. Aruba recommends deleting existing NAE scripts before an upgrade and then reinstalling the scripts after the upgrade. For more information, see the *Network Analytics Engine Guide*.

Manual configuration restore for software downgrade

To restore a previous configuration when downgrading to a previous version of software, follow these steps:

1. Use the **show checkpoint** command to see the saved checkpoints and ensure that you have a checkpoint that is an exact match of the target software version (see the **Image Version** column in the output of the command, for example, ML.10.xx.yyyy).
This checkpoint can be the startup-config-backup automatically created during the initial upgrade or any other manually created checkpoint for the target software version.
2. Copy the backup checkpoint into the startup-config.
3. Boot the switch to the target version (lower version), making sure to select **no** when prompted to save the current configuration.

Performing the upgrade

For additional upgrade and downgrade scenarios, including limitations of automatic upgrade and downgrade scenarios provided by the Configuration Migration Framework (CMF), refer to the [AOS-CX 10.12 Fundamentals Guide](#).



This version may contain a change of BootROM from the current running version. A BootROM update is a non-failsafe update. Do not interrupt power to the switch during the update process or the update could permanently damage the device.

1. Copy the new image into the non-current boot bank on the switch using your preferred method.
2. Depending on the version being updated, there may be device component updates needed. Preview any devices updates needed using the `boot system <BOOT-BANK>` command and entering `n` when asked to continue.

For example, if you copied the new image to the secondary boot bank and no device component updates are needed, you will see this:

```
switch# boot system secondary
Default boot image set to secondary.
Checking if the configuration needs to be saved...

Checking for updates needed to programmable devices...
Done checking for updates.

This will reboot the entire switch and render it unavailable
until the process is complete.
Continue (y/n)? n
```

In this example, three device updates will be made upon reboot, one of which is a non-failsafe device:

```
switch# boot system secondary
Default boot image set to secondary.
Checking if the configuration needs to be saved...

Checking for updates needed to programmable devices...
Done checking for updates.

2 device(s) need to be updated during the boot process.
The estimated update time is between 2 and 3 minute(s).
There may be multiple reboots during the update process.

1 non-failsafe device(s) also need to be updated.
Please run the 'allow-unsafe-updates' command to enable these updates.

This will reboot the entire switch and render it unavailable
until the process is complete.
Continue (y/n)? n
```

3. When ready to update the system, if a non-failsafe device update is needed, make sure the system will not have any power interruption during the process. Invoke the `allow unsafe updates` command to allow updates to proceed after a switch reboot. Proceed to step 4 within the configured time.

```
switch# config
switch(config)# allow-unsafe-updates 30
```

This command will enable non-failsafe updates of programmable devices for the next 30 minutes. You will first need to wait for all line and fabric modules to reach the ready state, and then reboot the switch to begin applying any needed updates. Ensure that the switch will not lose power, be rebooted again, or have any modules removed until all updates have finished and all line and fabric modules have returned to the ready state.

WARNING: Interrupting these updates may make the product unusable!

Continue (y/n)? **y**

Unsafe updates : allowed (less than 30 minute(s) remaining)

4. Use the `boot system <BOOT-BANK>` command to initiate the upgrade. On the switch console port an output similar to the following will be displayed as various components are being updated:

```
switch# boot system secondary
```

Default boot image set to secondary.

Checking if the configuration needs to be saved...

Checking for updates needed to programmable devices...

Done checking for updates.

3 device(s) need to be updated during the boot process.

The estimated update time is between 2 and 3 minute(s).

There may be multiple reboots during the update process.

This will reboot the entire switch and render it unavailable until the process is complete.

Continue (y/n)? **y**

The system is going down for reboot.

Looking for SVOS.

Primary SVOS: Checking...Loading...Finding...Verifying...Booting...

ServiceOS Information:

Version: <serviceOS_number>

Build Date: yyyy-mm-dd hh:mm:ss PDT

Build ID: ServiceOS:<serviceOS_number>:6303a2a501ba:202006171659

SHA: 6303a2a501bad91100d9e71780813c59f19c12fe

Boot Profiles:

0. Service OS Console

1. Primary Software Image [xx.10.11.1010]

2. Secondary Software Image [xx.10.12.1000]

Select profile(secondary):

ISP configuration:

Auto updates : enabled

Version comparisons : match (upgrade or downgrade)

Unsafe updates : allowed (less than 29 minute(s) remaining)

Advanced:

```

Config path      : /fs/nos/isp/config [DEFAULT]
Log-file path    : /fs/logs/isp [DEFAULT]
Write-protection : disabled [DEFAULT]
Package selection : 0 [DEFAULT]

3 device(s) need to be updated by the ServiceOS during the boot process.
The estimated update time by the ServiceOS is 2 minute(s).
There may be multiple reboots during the update process.

MODULE 'mc' DEVICE 'svos_primary' :
  Current version : '<serviceOS_number>'
  Write-protected : NO
  Packaged version : '<version>'
  Package name    : '<svos_package_name>'
  Image filename  : '<filename>.svos'
  Image timestamp : 'Day Mon dd hh:mm:ss yyyy'
  Image size      : 22248723
  Version upgrade needed

Starting update...

Writing...      Done.
Erasing...      Done.
Reading...      Done.
Verifying...    Done.
Reading...      Done.
Verifying...    Done.

Update successful (0.5 seconds).

reboot: Restarting system

```

Multiple components may be updated and several reboots will be triggered during these updates. When all component updates are completed, the switch console port will arrive at the login prompt with a display similar to following:

```

(C) Copyright 2017-2023 Hewlett Packard Enterprise Development LP

RESTRICTED RIGHTS LEGEND
Confidential computer software. Valid license from Hewlett Packard Enterprise
Development LP required for possession, use or copying. Consistent with FAR
12.211 and 12.212, Commercial Computer Software, Computer Software
Documentation, and Technical Data for Commercial Items are licensed to the
U.S. Government under vendor's standard commercial license.

We'd like to keep you up to date about:
* Software feature updates
* New product announcements
* Special events
Please register your products now at: https://asp.arubanetworks.com

switch login:

```



Aruba recommends waiting until all upgrades have completed before making any configuration changes.

Aruba is committed to ensuring you have the resources you need to be successful. Check out these learning and documentation resources:

- AOS-CX switch software documentation portal: https://www.arubanetworks.com/techdocs/AOS-CX/help_portal/Content/home.htm
- AOS-CX 10.11 playlist of technical training videos on YouTube: https://www.youtube.com/playlist?list=PLsYGHuNuBZcbWPEjjHuVMqP-Q_UL3CskS

A Security Bulletin is the first published notification of security vulnerabilities and is the only communication vehicle for security vulnerabilities.

- Fixes for security vulnerabilities are not documented in manuals, release notes, or other forms of product documentation.
- A Security Bulletin is released when all vulnerable products still in support life have publicly available images that contain the fix for the security vulnerability.

The Aruba security policy can be found at <https://www.arubanetworks.com/en-au/support-services/sirt/>. Security bulletins can be found at <https://www.arubanetworks.com/en-au/support-services/security-bulletins/>. You can sign up at https://sirt.arubanetworks.com/mailman/listinfo/security-alerts_sirt.arubanetworks.com to initiate a subscription to receive future Aruba Security Bulletin alerts via email.