



## **Release Notes for Cisco 8000 Series Routers, Release 7.0.12**

<b>Cisco 8000 Series Routers</b>	<b>2</b>
What's New in Cisco IOS XR Release 7.0.12	3
Caveats	7
Supported Packages and System Requirements	7
Other Important Information	11
 <b>Full Cisco Trademarks with Software License</b>	 <b>12</b>

Revised: February 4, 2021

# Cisco 8000 Series Routers



---

**Note** Explore the [Content Hub](#), the all new portal that offers an enhanced product documentation experience.

- Use faceted search to locate content that is most relevant to you.
- Create customized PDFs for ready reference.
- Benefit from context-based recommendations.

Get started with the Content Hub at [content.cisco.com](https://content.cisco.com) to craft a personalized documentation experience.

Do provide feedback about your experience with the Content Hub.

---

The Cisco 8000 Series combines Cisco's revolutionary IOS XR software, and a set of clean-sheet chassis to deliver a breakthrough in high-performance routers. The 8000 Series comprises a full range of feature-rich, highly scalable, deep-buffered, and 400G-optimized. These routers range from 10.8 Tbps in a 1-RU to 2-RU footprint to an industry-leading, rack-mountable modular system capable of ~260 Tbps of full duplex, line rate forwarding.

The Cisco 8000 Series includes two distinct router architectures- 8800 Series and 8200 Series.

The 8000 series routers deliver significant hardware improvements that includes:

- State-of-the-art redundant fans
- Network Equipment Building System (NEBS)-compliant air filters with doors for simplified line card access
- Future-proof power capacity with power-saving internal distribution
- New power supplies for power feed redundancy with reduced provisioning
- Cable management for up to 864 fibers

The Cisco IOS XR7 network operating system running on Cisco 8000 Series is the enhanced version of Cisco IOS XR software. The enhancements are designed to make Cisco IOS XR7 trusted, simple, and automatable.

## Trusted Network

Building a secure and trustworthy network infrastructure is the one of Cisco's major objective.

The ability to verify that a Cisco device is genuine and running authentic code depends on Cisco Secure Boot. Cisco Secure Boot ensures that the device boot image is genuine and untampered. With advanced signing technology, IOS XR7 establishes software integrity enforcement and measurement.

Even if booted securely, a router may have vulnerabilities at runtime, which may remain undetected for a long time. IOS XR7 leverages Integrated Measurement Architecture (IMA) to significantly enhance security by verifying the integrity of the software at runtime.

## Simple Network

The IOS XR7 operating system runs across diverse network devices that include proprietary hardware, third party hardware and virtual network functions (VNF). Also, with IOS XR7, all critical components are modularized as packages so that customers load only what they need. Cisco software packages, customized packages, third-party software packages, as well as the router configuration,

are pulled together into a single Cisco software image that is known as a Golden ISO. Customized images can now be installed consistently and with confidence across devices in the network.

### **Automatable Network**

IOS XR 7 embraces model-driven telemetry and APIs to automate your network tasks and functions. IOS XR7 supports a comprehensive list of both native and industry-driven OpenConfig models to exchange configuration and operational data between a client and a server. To keep a check on internal system parameters, IOS XR7 supports a service processor called Board Management Controller (BMC). BMC provides specialized controllers that monitor the state of a network device. It enables monitoring and management of various aspects of the system, such as device health, log events for failure analysis, environmental control, and firmware upgrades. BMC also helps in recovering the router in case of failures.

## **What's New in Cisco IOS XR Release 7.0.12**

Cisco is continuously enhancing the product with every release and this section covers a brief description of key features and enhancements. It also includes links to detailed documentation, where available.

### **Software**

- Routing Protocols—[BGP](#), [OSPF](#), and [IS-IS](#)
- [IPv4 and IPv6 Routing](#)
- [Segment Routing](#)
- [MPLS](#)
- [Multicast](#)
- [Quality of Service \(Qos\)](#)
- [Access List \(ACL\)](#)
- [NetFlow](#)
- [Traffic Mirroring using ERSPAN](#)
- [IPinIP](#)
- [CDP](#)
- [LLDP](#)
- [Priority Flow Control](#)
- [System Management](#)
- [System Security](#)
- [Interfaces:](#)
  - [Physical Interface and Physical sub-interface—100G, 400G, 40G, and 10G](#)
  - [Bundle](#)

## Hardware

- Cisco 8201, Cisco 8808 and Cisco 8812 chassis
- 36-port QSFP56-DD 400 GbE line card
- 48-port QSFP28 100 GbE line card
- Cisco 8812 and Cisco 8808 fabric card

### Cisco 8201 Chassis


*Figure 1: Cisco 8201*



The Cisco 8201 (8201-SYS) is a fixed chassis router. This chassis delivers up to 10.8 Tbps of network bandwidth with dramatically lower power consumption than contemporary 10 Tbps systems.

### Cisco 8808 Chassis


*Figure 2: Cisco 8808*



The Cisco 8808 (8808-SYS) is a modular chassis router that supports upto 8 line cards, 8 fabric cards and 2 route processor cards. This chassis delivers up to 115.2 Tbps bandwidth.

## Cisco 8812 Chassis


*Figure 3: Cisco 8812*



The Cisco 8812 (8812-SYS) is a modular chassis router that supports up to 12 line cards, 8 fabric cards and 2 route processor cards. This chassis delivers up to 14.4 Tbps per line card through 100 and 400 Gigabit Ethernet (GbE) ports.

## 36-port QSFP56-DD 400 GbE Line Card


*Figure 4: 36-port 400 GbE Line Card*



The 36-port QSFP56-DD 400 GbE line card (8800-LC-36FH) provides 14.4 Tbps via 36 QSFP56-DD ports. It provides up to 144 ports of 100 GbE via breakout and supports QSFP+, QSFP28, and QSFP56-DD modules.

### 48-port QSFP28 100 GbE Line Card


*Figure 5: 48-port 100 GbE Line Card*



The 48-port QSFP28 100 GbE line card (8800-LC-48H) provides 4.8 Tbps with MACsec support on all ports. It also supports QSFP+ optics 40G (4x10G breakout only).


### Cisco 8812 Fabric Card

*Figure 6: Cisco 8812 FC*



### Cisco 8808 Fabric Card

*Figure 7: Cisco 8808 FC*



The Cisco 8812 and Cisco 8808 chassis is powered by 8 fabric cards (8812-FC and 8808-FC) that provide 7+1-line rate redundancy. In addition, the fabric card supports a separate operational mode with 4+1 fabric card redundancy to provide an entry-level option for systems with only the 48-port 100 GbE line card.



## Caveats

This section lists the open bugs for Cisco 8000 Series Routers.

Bug ID	Headline
<a href="#">CSCvt27030</a>	On booting a Cisco 8201 router with XR 7012 image, show fpd may display BMC fpps in NOT READY state.
<a href="#">CSCvt43772</a>	Performing a commit replace of entire router configuration followed by loading of configuration or rollback of configuration may cause router to be in inconsistent state.

## Supported Packages and System Requirements

### Supported Hardware

For a complete list of supported hardware and [ordering information](#), see the [Cisco 8000 Series Data Sheet](#).

### Release 7.0.12 Packages

The Cisco IOS XR software is composed of a base image (ISO) that provides the XR infrastructure. The ISO image is made up of a set of packages (also called RPMs). These packages are of three types:

- A mandatory package that is included in the ISO
- An optional package that is included in the ISO
- An optional package that is not included in the ISO

To determine the Cisco IOS XR Software packages installed on your router, log in to the router and enter the **show install active** command:

To know about all the RPMs installed including XR, OS and other components use the **show install active all** command

The software modularity approach provides a flexible model that allows you to install a subset of IOS XR packages on devices based on your individual requirements. All critical components are modularized as packages so that you can select the features that you want to run on your router.



---

**Note** The above show command output displays mandatory packages that are installed on the router. To view the optional and bug fix RPM packages, first install the package and use the **show install active summary** command.

---

## Determine Software Version

Log in to the router and enter the **show version** command:

```
RP/0/RP0/CPU0# show version
Mon Oct 12 14:43:39.609 EDT
Cisco IOS XR Software, Version 7.2.12 LNT
Copyright (c) 2013-2020 by Cisco Systems, Inc.
```

```
Build Information:
Built By      : <username>
Built On     : Mon Oct 12 08:25:38 UTC 2020
Build Host   : iox-lnx-060
Workspace    : /auto/srcarchive17/prod/7.2.12/8000/ws
Version     : 7.2.12
Label       : 7.2.12-7212_brusilva_1012_renumber
```

```
cisco 8000 (D-1530 @ 2.40GHz)
System uptime is 15 minutes
```

```
RP/0/RP0/CPU0:router# show version
Wed Jan 15 21:45:57.239 UTC
Cisco IOS XR Software, Version 7.0.12 LNT
Copyright (c) 2013-2020 by Cisco Systems, Inc.
```

```
Build Information:
Built By      : <username>
Built On     : Sat Mar 14 14:18:11 UTC 2020
Build Host   : iox-ucs-033
Workspace    : /auto/srcarchive17/prod/7.0.12/8000/ws
Version     : 7.0.12
Label       : 7.0.12
```

```
cisco 8000
System uptime is 2 days, 18 hours, 44 minutes
```

## Determine Firmware Support

Log in to the router and enter **show fpd package** command:

### Cisco 8201

```
RP/0/RP0/CPU0:router# show fpd package
```

Field Programmable Device Package					
Card Type	FPD Description	Req Reload	SW Ver	Min Req SW Ver	Min Req Board Ver
8201	Bios	YES	1.15	1.15	0.0
	BiosGolden	YES	1.15	1.15	0.0
	BmcFitPrimary	YES	0.550	0.550	0.0
	BmcFpga	YES	1.00	1.00	0.0
	BmcFpgaGolden	YES	1.00	0.86	0.0
	BmcTamFw	YES	5.06	5.06	0.0
	BmcTamFwGolden	YES	5.06	5.05	0.0
	BmcUbootPrimary	YES	1.00	1.00	0.0
	IoFpga	YES	1.00	1.00	0.1
	IoFpgaGolden	YES	1.00	0.48	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.02	11.02	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	x86Fpga	YES	1.00	1.00	0.0
	x86FpgaGolden	YES	1.00	0.48	0.0
	x86TamFw	YES	5.06	5.06	0.0
	x86TamFwGolden	YES	5.06	5.05	0.0
PWR-1.4KW-ACPE	DC-PrimMCU	NO	31.00	31.00	0.0
	DC-SecMCU	NO	16.00	16.00	0.0



PWR-1.4KW-ACPE-TLV	DC-PrimMCU	NO	31.00	31.00	0.0
	DC-SecMCU	NO	16.00	16.00	0.0
PWR-1.4KW-ACPI	DC-PrimMCU	NO	31.00	31.00	0.0
	DC-SecMCU	NO	16.00	16.00	0.0
PWR-1.4KW-ACPI-TLV	DC-PrimMCU	NO	31.00	31.00	0.0
	DC-SecMCU	NO	16.00	16.00	0.0
PWR-2KW-ACPE	PO-PrimMCU	NO	17.54	17.54	0.0
PWR-2KW-ACPE-TLV	PO-PrimMCU	NO	17.54	17.54	0.0
PWR-2KW-ACPI	PO-PrimMCU	NO	17.56	17.56	0.0
PWR-2KW-ACPI-TLV	PO-PrimMCU	NO	17.56	17.56	0.0
PWR-2KW-DCPE	PO-PrimMCU	NO	1.07	1.07	0.0
PWR-2KW-DCPE-TLV	PO-PrimMCU	NO	1.07	1.07	0.0
PWR-2KW-DCPI	PO-PrimMCU	NO	1.07	1.07	0.0
PWR-2KW-DCPI-TLV	PO-PrimMCU	NO	1.07	1.07	0.0

## Cisco 8812

RP/0/RP0/CPU0:router# show fpd package

Field Programmable Device Package					
Card Type	FPD Description	Req Reload	SW Ver	Min Req SW Ver	Min Req Board Ver
8800-LC-36H	Bios	YES	1.15	1.15	0.0
	BiosGolden	YES	1.15	1.15	0.0
	EthSwitch	YES	1.01	1.01	0.0
	EthSwitchGolden	YES	1.01	0.07	0.0
	IoFpga	YES	1.01	1.01	0.0
	IoFpgaGolden	YES	1.01	0.08	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.02	11.02	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	x86Fpga	YES	1.01	1.01	0.0
	x86FpgaGolden	YES	1.01	0.33	0.0
	x86TamFw	YES	5.06	5.06	0.0
	x86TamFwGolden	YES	5.06	5.05	0.0
8800-LC-48H	Bios	YES	1.15	1.15	0.0
	BiosGolden	YES	1.15	1.15	0.0
	EthSwitch	YES	1.01	1.01	0.0
	EthSwitchGolden	YES	1.01	0.07	0.0
	IoFpga	YES	1.01	1.01	0.0
	IoFpgaGolden	YES	1.01	0.08	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.02	11.02	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	x86Fpga	YES	1.01	1.01	0.0
	x86FpgaGolden	YES	1.01	0.33	0.0
	x86TamFw	YES	5.06	5.06	0.0
	x86TamFwGolden	YES	5.06	5.05	0.0

8800-RP	Bios	YES	1.15	1.15	0.0
	BiosGolden	YES	1.15	1.15	0.0
	BmcFitPrimary	YES	0.550	0.550	0.0
	BmcFpga	YES	1.01	1.01	0.0
	BmcFpgaGolden	YES	1.01	0.19	0.0
	BmcTamFw	YES	5.06	5.06	0.0
	BmcTamFwGolden	YES	5.06	5.05	0.0
	BmcUbootPrimary	YES	1.00	1.00	0.0
	EthSwitch	YES	1.00	1.00	0.0
	EthSwitchGolden	YES	1.00	0.07	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.02	11.02	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	TimingFpga	YES	1.00	1.00	0.0
	TimingFpgaGolden	YES	1.00	0.11	0.0
	x86Fpga	YES	1.02	1.02	0.0
	x86FpgaGolden	YES	1.02	0.24	0.0
	x86TamFw	YES	5.06	5.06	0.0
	x86TamFwGolden	YES	5.06	5.05	0.0
<hr/>					
8808-FAN	FTFPGAGolden	NO	1.00	0.16	0.0
	FTFPGAUpgrade	NO	1.00	1.00	0.0
<hr/>					
8808-FC	IoFpga	YES	1.00	1.00	0.0
	IoFpgaGolden	YES	1.00	0.05	0.0
<hr/>					
8812-FAN	FTFPGAGolden	NO	1.00	0.16	0.0
	FTFPGAUpgrade	NO	1.00	1.00	0.0
<hr/>					
8812-FC	IoFpga	YES	1.00	1.00	0.0
	IoFpgaGolden	YES	1.00	0.05	0.0
	Retimer	YES	2.00	2.00	0.0
<hr/>					
8818-FAN	FTFPGAGolden	NO	1.00	0.16	0.0
	FTFPGAUpgrade	NO	1.00	1.00	0.0
<hr/>					
8818-FC	IoFpga	YES	1.00	1.00	0.0
	IoFpgaGolden	YES	1.00	0.05	0.0
	Retimer	YES	2.00	2.00	0.0
<hr/>					
PSU6.3KW-HV	DT-LogicMCU	NO	4.11	4.11	0.0
	DT-PrimMCU	NO	4.01	4.01	0.0
	DT-SecMCU	NO	4.00	4.00	0.0
<hr/>					
PWR-4.4KW-DC-V3	DT-LogicMCU	NO	3.00	3.00	0.0
	DT-Prim1MCU	NO	3.00	3.00	0.0
	DT-Prim2MCU	NO	3.00	3.00	0.0
	DT-Sec1MCU	NO	3.00	3.00	0.0
	DT-Sec2MCU	NO	3.00	3.00	0.0
<hr/>					
PWR-4.8KW-DC	PrimMCU	NO	0.02	0.02	0.0



**Note** The **show fpd package** command lists 8818-FC, and 8818-FAN. However, these hardware are not supported. There is no functionality impact on the router.

## Other Important Information

- The warning message that the smart licensing evaluation period has expired is displayed in the console every hour. There is, however, no functionality impact on the device. The issue is seen on routers that don't have the Flexible Consumption licensing model enabled. To stop the repetitive messaging, register the device with the smart licensing server and enable the Flexible Consumption model. Later load a new registration token.

To register the device with the smart licensing server, see the [Registering and Activating Your Router](#).

- When you execute the **show tech-support** command, a temporary directory is created and the related data is stored in this directory. This directory is deleted after the command is completed. For example,

```
Router#run ls -ltr
drwxrwxrwx. 3 root root show-tech-fabric-link-incl-loc-010cpu0_2.tgz
```

In case, you terminate the **show tech-support** command manually, we recommend you to delete the corresponding show tech directory if not needed.

## Supported Transceiver Modules

To determine the transceivers that Cisco hardware device supports, refer to the [Transceiver Module Group \(TMG\) Compatibility Matrix Tool](#).

# Full Cisco Trademarks with Software License

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)





**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA 95134-1706  
USA

**Asia Pacific Headquarters**  
CiscoSystems(USA)Pte.Ltd.  
Singapore

**Europe Headquarters**  
CiscoSystemsInternationalBV  
Amsterdam,TheNetherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the  
Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).