

# Release Notes for Cisco RV130/RV130W Routers Firmware Version 1.0.0.21

## **March 2014**

This document describes known issues in Cisco RV130/RV130W Firmware Version 1.0.0.21.

## **Contents**

**Known Issues, page 2**

**Related Information, page 3**

## Known Issues

### Caveats Acknowledged in Firmware Version 1.0.0.21

**Problem:** If users set outbound firewall access rules to Deny, then create an Internet access policy to permit a specific website, the access rule does not work and other websites are also permitted. (CSCun04513)

**Solution:** None.

**Problem:** If users enable Email settings, set **Authentication with SMTP Server** to Login and enter a secondary email address to which to send logs, email is not sent to the secondary address provided. (CSCum76056)

**Solution:** Disable the Login authentication option.

**Problem:** STP does not work accurately with Link Aggregation Groups (LAG). For example, if ports 1 and 2 are included in a LAG, the STP root bridge is wrong after the link status changes for port 1. (CSCum50055)

**Solution:** Disable LAG.

**Problem:** The WDS links is not up if the peer MAC address format is incorrect. For example, users enter 001122334455 instead of 00:11:22:33:44:55. (CSCum59546)

**Solution:** Change the MAC address format to '00:11:22:33:44:55'.

**Problem:** Wireless clients may not be able to access the Internet when roaming between the device and another access point on the LAN side. (CSCum42666)

**Solution:** Enable WAN QoS or STP on LAN ports.

**Problem:** When the syslogs reach 1000, the device does not email logs to users. (CSCum72888)

**Solution:** Use the syslogs server to view the messages or check local syslogs.

**Problem:** VLAN ID 80 does not work. (CSCum31734)

**Solution:** Use other VLAN IDs.

**Problem:** If the PPTP tunnel is established and users create a new VLAN, the PPTP clients are offline and cannot connect again. (CSCum72910)

**Solution:** Go to the PPTP Settings page and save again.

**Problem:** If Dead Peer Detection is enabled, the IPsec VPN tunnel may reconnect in case of heavy traffic. (CSCum72973)

**Solution:** Limit heavy traffic over the VPN tunnel.

## Related Information

Support	
Cisco Small Business Support Community	<a href="http://www.cisco.com/go/smallbizsupport">www.cisco.com/go/smallbizsupport</a>
Cisco Small Business Support and Resources	<a href="http://www.cisco.com/go/smallbizhelp">www.cisco.com/go/smallbizhelp</a>
Cisco Small Business Firmware Downloads	<a href="http://www.cisco.com/go/software">www.cisco.com/go/software</a> Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco Small Business RV Series Routers	<a href="http://www.cisco.com/go/smallbizrouters">www.cisco.com/go/smallbizrouters</a>
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	<a href="http://www.cisco.com/web/partners/sell/smb">www.cisco.com/web/partners/sell/smb</a>
Cisco Small Business Home	<a href="http://www.cisco.com/smb">www.cisco.com/smb</a>

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2014 Cisco Systems, Inc. All rights reserved.

OL-31728-01