



**Firmware Release Note** 

USG60W

Release V4.13(AAKZ.1)C0

Date: Aug 30, 2015 Author: Shang Lee Project Leader: Shang Lee



# Contents

Supported Platforms:	3
Versions:	3
Files lists contains in the Release ZIP file	3
Read Me First	4
Design Limitations:	5
APP Patrol	5
Build in Service	5
DNS	5
GUI	5
Interface	6
IPsec VPN	6
SSL VPN	7
L2TP VPN	8
User Aware	8
IPv6	9
Device-HA	9
MAC Authentication	9
Wireless	.10
Known Issues:	11
IPSec VPN	.11
IPv6	.12
AppPatrol	.12
SSL VPN	.12
System	.13
Anti-Virus	.13
Wireless	.13
Features: V4.13(AAKZ.1)C0	14
Features: V4.13(AAKZ.0)C0	15
Features: V4.11(AAKZ.2)C0	21
Features: V4.11(AAKZ.1)C0	22
Features: V4.11(AAKZ.0)C0	23
Features: V4.10(AAKZ.2)C0	28
Features: V4.10(AAKZ.0)C0	33
Appendix 1. Firmware upgrade / downgrade procedure	34
Appendix 2. SNMPv2 private MIBS support	35
Appendix 3. Firmware Recovery	36



# **ZyXEL USG60W**

# Release V4.13(AAKZ.1)C0

# **Release Note**

Date: Aug 30, 2015

# **Supported Platforms:**

ZyXEL USG60W

# Versions:

ZLD Version: V4.13(AAKZ.1) | 2015-08-24 20:35:45 Boot Module Version: V1.02 | Jul 10 2014 14:05:59

# Files lists contains in the Release ZIP file

#### File name: 413AAKZ1C0.bin

Purpose: This binary firmware image file is for normal system update.

Note: The firmware update may take five or more minutes depending on the scale of device configuration. The more complex the configuration, the longer the update time. Do not turn off or reset the ZyWALL/USG while the firmware update is in progress. The firmware might get damaged, if device loss power or you reset the device during the firmware upload. You might need to refer to Appendix 3 of this document to recover the firmware.

#### File name: 413AAKZ1C0.conf

Purpose: This ASCII file contains default system configuration commands.

**File name: 413AAKZ1C0.pdf** Purpose: This release file.

#### File name: 413AAKZ1C0.ri

Purpose: This binary firmware recovery image file is for emergent system firmware damage recovery only.

Note: The ZyWALL/USG firmware could be damaged, for example by the power going off or pressing Reset button during a firmware update.



#### File name: 413AAKZ1C0-MIB.zip

Purpose: The MIBs are to collect information on device. The focus of the MIBs is to let administrators collect statistical data and monitor status and performance. The zip file includes several files: 413AAKZ1C0-enterprise.mib, 413AAKZ1C0-private.mib, ZYXEL-ES-SMI.MIB, ZYXEL-ES-CAPWAP.MIB, ZYXEL-ES-COMMON.MIB and ZYXEL-ES-ProWLAN.MIB. Please import ZYXEL-ES-SMI.MIB first.

#### File name: 413AAKZ1C0-opensource-list.xls

Purpose: This file lists the open source packages.

#### File name: 3G dongle compatibility table v106.xlsx, 3G patch file v106.wwan

Purpose: Mobile broadband dongle support list.

# **Read Me First**

- 1. The system default configuration is summarized as below:
  - The default device administration username is "admin", password is "1234".
  - The default LAN interface is ge3, which are P3 port on the front panel. The default IP address of lan1 is 192.168.1.1/24.
  - By default, WWW/SSH/SNMP service can only be accessed from LAN subnet.
  - The default WAN interface is ge1, and the secondary WAN interface is ge2. These two interfaces will automatically get IP address using DHCP by default.
- 2. It is recommended that user backs up "startup-config.conf" file first before upgrading firmware. The backup configuration file can be used if user wants to downgrade to an older firmware version.
- 3. If user upgrades from previous released firmware to this version, there is no need to restore to system default configuration.
- 4. When getting troubles in configuring via GUI (popup java script error, etc), it is recommended to clear browser's cache first and try to configure again.
- 5. To reset device to system default, user could press RESET button for 5 seconds and the device would reset itself to system default configuration and then reboot.
  - Note: After resetting, the original configuration would be removed. It is recommended to backup the configuration before this operation.
- If ZyWALL/USG can't reboot successfully after firmware upgrade, please refer to Appendix 3: Firmware Recovery.



# **Design Limitations:**

Note: Design Limitations described the system behavior or limitations in current version. They will be created into knowledge base.

# **APP Patrol**

1. [SPR: 140425359, 140425375]

[Symptom]

If a profile is to block browser only (ex. Chrome, IE), it may not take effect because "user access website" have higher priority for matching.

### **Build in Service**

1. [SPR: 061208575]

[Symptom]

If users change port for built-in services (FTP/HTTP/SSH/TELNET) and the port conflicts with other service or internal service, the service might not be brought up successfully. The internal service ports include 50001/10443/10444/1723/2601-2604/953. Users should avoid using these internal ports for built-in services.

[Workaround]

Users should avoid using these internal ports for built-in services.

### DNS

1. [SPR: 140425458]

[Symptom]

DUT does not support \*.com A-record PTR.

2. [SPR: 150122977]

[Symptom]

DNS security option will deny device local out DNS query

[Condition]

- 1. Edit the customize rule of DNS security option, and set the query recursion as deny.
- 2. If device's WAN IP address is in the customize address range, device local-out DNS query will be deny.

### GUI

1. [SPR: 100415854]

[Symptom]

The GUI's initial help page's behavior was wrong.

[Condition]

1. In the GUI Interface page press the Site Map page, it will pop up the window.



- 2. Press the question mark(?), GUI will open the Site Map's help page.
- 3. Close the help and Site Map window, press the Interface page's Help link.
- 4. It still open the Site Map's help page.[SPR: 100914249][Symptom]IE7/8 sometimes shows "Stop running this script? A script on this page is causing Internet Explorer to run slowly. If it continues to run, your computer may become unresponsive." when configuring device. Please update IE patch: <u>http://support.microsoft.com/kb/175500</u> for fixing this issue

# Interface

1. [SPR: 100105242, 100105292]

### [Symptom]

PPTP might not be able to connect successfully if it is configured via Installation Wizard/Quick Setup. This is because:

- 1. Installation Wizard/Quick Setup only allows PPTP based interface to be configured with Static IP.
- Installation Wizard/Quick Setup doesn't allow user to configure PPTP based interface's Gateway IP Address. This may cause PPTP cannot connect successfully if the PPTP Server IP is not at the same subnet with PPTP's based interface

[Workaround]

Before dial PPTP connection, configure the Gateway IP of PPTP interface's based interface

### **IPsec VPN**

1. [SPR: 070814168]

### [Symptom]

VPN tunnel could not be established when:

- 1. a non ZyWALL/USG peer gateway reboot and
- 2. ZyWALL/USG has a previous established Phase 1 with peer gateway, and the Phase 1 has not expired yet. Under those conditions, ZyWALL/USG will continue to use the previous phase 1 SA to negotiate the Phase 2 SA. It would result in phase 2 negotiation to fail.

[Workaround]

User could disable and re-enable phase 1 rule in ZyWALL/USG or turn on DPD function to resolve problem.

2. [SPR: 100429119]

[Symptom]

VPN tunnel might be established with incorrect VPN Gateway

[Condition]

- 1. Prepare 2 ZyWALL/USG and reset to factory default configuration on both ZyWALL/USGs
- 2. On ZyWALL/USG-A:



- 1. Create 2 WAN interfaces and configure WAN1 as DHCP Client
- 2. Create 2 VPN Gateways. The "My Address" is configured as Interface type and select WAN1 and WAN2 respectively
- 3. Create 2 VPN Connections named VPN-A and VPN-B accordingly which bind on the VPN Gateways we just created
- 3. On ZyWALL/USG-B
  - 1. Create one WAN interface
  - Create one VPN Gateway. The Primary Peer Gateway Address is configured as WAN1 IP address of ZyWALL/USG-A and the Secondary Peer Gateway Address is configured as WAN2 IP address of ZyWALL/USG-A
- 4. Connect the VPN tunnel from ZyWALL/USG-B to ZyWALL/USG-A and we can see VPN-A is connected on ZyWALL/USG-A
- 5. Unplug WAN1 cable on ZyWALL/USG-A
- 6. After DPD triggered on ZyWALL/USG-B, the VPN Connection will be established again
- 7. On ZyWALL/USG-A, VPN-A is connected. But actually ZyWALL/USG-B should connect to VPN-B after step 5.

[Workaround] Change the WAN1 setting of ZyWALL/USG-A to Static IP

3. [SPR: 140304057]

[Symptom]

After inactivating GRE over IPsec, old connection may remain if the traffic flows continuously. This may cause traffic bounded with old connection.

[Workaround] Stop traffic for 180 seconds and the internal connection record will time out.

4. [SPR: 140416738]

[Symptom]

Ignore don't fragment setting cannot take effect immediately if there already existed the same connection.

[Workaround] Stop traffic for 180 seconds and the internal connection record will time out.

### **SSL VPN**

1. Following are the table list for SSL VPN supporting applications and operating systems:

Applications Operating System	Full Tunnel Mode	Reverse Proxy Mode File Sharing(Web-based Application)	RDP	VNC
Windows 7 (X64) (SP1)	Internet Explorer 8.x, 9.x, 10.x, 11.x	Internet Explorer 8.x, 9.x, 10.x, 11.x	Internet Explorer 8.x, 9.x, 10.x, 11.x	Internet Explorer 8.x, 9.x, 10.x, 11.x
	Chrome 44.x or previous version	Chrome 44.x or previous version		Chrome 44.x or previous version
Java 7	Firefox latest version	Firefox latest version		Firefox latest version
-	Opera latest version	-		-



	Safari latest version	Safari latest version		Safari latest version
Windows 7 (X32) (SP1)	Internet Explorer 8.x, 9.x, 10.x, 11.x	Internet Explorer 8.x, 9.x, 10.x, 11.x	Internet Explorer 8.x, 9.x, 10.x, 11.x	Internet Explorer 8.x, 9.x, 10.x, 11.x
	Chrome 44.x or previous version	Chrome 44.x or previous version		Chrome 44.x or previous version
Java 7		Firefox latest version		Firefox latest version
-	Opera latest version	-		-
	Safari latest version	Safari latest version		Safari latest version
Windows 8 (X64)	Internet Explorer 10.x, 11.x	Internet Explorer 10.x, 11.x	Internet Explorer 10.x, 11.x	Internet Explorer 10.x, 11.x
Java 7	Chrome 44.x or previous version	Chrome 44.x or previous version		Chrome 44.x or previous version
	Firefox latest version	Firefox latest version		Firefox latest version
	Safari latest version	Safari latest version		Safari latest version
Windows 8 (X32)	Internet Explorer 10.x, 11.x	Internet Explorer 10.x, 11.x	Internet Explorer 10.x, 11.x	Internet Explorer 10.x, 11.x
Java 7	Chrome 44.x or previous version	Chrome 44.x or previous version		Chrome 44.x or previous version
	Firefox latest version	Firefox latest version		Firefox latest version
	Safari latest version	Safari latest version		Safari latest version
MAC OSX 10.9 Java 7	Safari 7.0.x Chrome 33.0.x Firefox 27.0.x	Safari 7.0.x Firefox 27.0.x	Not support	Firefox 27.0.x

#### 2. [SPR: 100419034]

[Symptom]

SSLVPN of VNC cannot work if user connects VNC application by FQDN.

### **L2TP VPN**

1. Following are the table list for L2TP VPN supporting L2TP client and operating systems:

L2TP Client	OS type	Client Version
Windows L2TP client	Windows 7 32/64 Windows 8 32/64	
iPhone/iPAD L2TP client	iPhone5 iPAD	6.1.2 6.1.2
Android L2TP client	Google Phone	
Mac L2TP client	X10.8.3	

2. [SPR: N/A]

[Symptom]

L2TP connection will break sometimes with Android device. This issue comes from the L2TP Hollow packet will not by replied by Android system.

#### **User Aware**

1. [SPR: 070813119] [Symptom]



Device supports authenticating user remotely by creating AAA method which includes AAA servers (LDAP/AD/Radius). If a user uses an account which exists in 2 AAA server and supplies correct password for the latter AAA server in AAA method, the authentication result depends on what the former AAA server is. If the former server is Radius, the authentication would be granted, otherwise, it would be rejected.

### [Workaround]

Avoid having the same account in AAA servers within a method.

# IPv6

- 1. HTTP/HTTPS not support IPv6 link local address in IE7 and IE8.
- Windows XP default MS-DOS FTP client cannot connection to device's FTP server via iPv6 link-local address.
- 3. [SPR: 110803280]

[Symptom]

Safari cannot log in web with HTTPS when using IPv6

4. [SPR: 110803293]

[Symptom]

Safari fails to redirect http to https when using IPv6

5. [SPR: 110803301]

[Symptom]

Safari with IPv6 http login when change web to System > WWW, it pop up a logout message. (HTTP redirect to HTTPS must enable)

# **Device-HA**

1. [SPR: N/A]

[Symptom]

Backup may send out traffic through its physical MAC address when booting system or during device-HA syncing (a short period)

[WORKAROUND]

Set short ARP timeout value on monitored interface's switch and gateway side.

# **MAC Authentication**

1. [SPR: 150127103]

[Symptom]

Client use Internal MAC-Auth connection Auth. Server can't get IP successful.

#### [WORKAROUND]

Set short ARP timeout value on monitored interface's switch and gateway side.

#### Wireless



1. [SPR: 150127103]

# [Symptom]

MAC authentication use internal and auth. method set USG, wireless client can't get IP successful.

# **Known Issues:**

Note: These known issues represent current release so far unfix issues. And we already plan to fix them on the future release.

ZyXEL

# **IPSec VPN**

1. [SPR: 120110586]

[Symptom]

When set IPsec VPN with certificate and enable x.509 with LDAP, the VPN session must dial over two times and the session will connect successfully

- 2. [SPR: 140317624]
  - [Symptom]

DUT fails to fall back using primary WAN port when all DUT WAN's IP address were same subnet.

3. [SPR: 140818615]

[Symptom]

After Enable and Disable NAT rule, IPsec VPN traffic cannot forward to LAN subnet immediately.

- [Condition]
  - 1. Topology:

PC1 --- LAN1 USG60W WAN1 ---- WAN1 USG60 LAN1 --- PC2 & PC3

2. USG60W

WAN1: 10.1.4.45/24

WAN2: 192.168.9.x/24 (Can reach to 172.23.x.x network through NAT router.) LAN1: 192.168.181.x/24

PC1: 192.168.181.33

3. USG60

WAN1: 10.1.6.79/24 LAN1: 192.168.1.1/24 PC2: 192.168.1.33 PC3: 192.168.1.34

- 4. USG60 sets a policy route, src=192.168.1.0/24, dst=172.0.0.0/8, next-hop=VPN tunnel USG60W sets
  - 1. policy route, src= 172.0.0.0/8, dst=192.168.1.0/24, next-hop=VPN tunnel
  - 2. policy route, src=192.168.1.0/24, dst=172.0.0.0/8, next-hop=WAN2
- 5. PC2 ping 172.23.x.x is OK
- 6. Add a 1:1NAT rule which is from WAN1 10.1.6.79 mapping to 192.168.1.34 (PC3) on USG60.

# ZyXEL

#### www.zyxel.com

- 7. PC2 ping 172.23.x.x will fail now.
- 8. Disable 1:1 NAT rule.
- 9. PC2 still cannot ping to 172.23.x.x.

Need to reboot device or wait several minutes, it works.

4. [SPR: 141209575]

### [Symptom]

IPsec VPN tunnel sometimes can be built up while initiator and responder devices use CA with the same subject name in IKE authentication. This tunnel should not be allowed to build.

5. [SPR: 150213841]

#### [Symptom]

Not support IKEv2 VPN Configuration Provisioning, so the configuration may apply failed in the following conditions.

[Condition]

- 1. Create phase1 rule a1(ikev1) and a2(ikev2).
- 2. Create phase2 rule b with VPN gateway rule a1.
- 3. Add one VPN provisioning rule with VPN connection rule b.
- 4. Change VPN connection rule b from a1 to a2.
- 5. Reboot device, it will apply configuration fail.

### IPv6

1. [SPR: 131226738]

[Symptom]

Only one prefix delegation can be added in IPv6 address assignment.

2. [SPR: 141125082]

[Symptom]

DHCPv6 relay cannot work.

### **AppPatrol**

1. [SPR: 140605136]

[Symptom]

[App Patrol] Cannot block Skype off-line message

### SSL VPN

- 1. [SPR: N/A]
  - [Symptom]

Windows 7 users cannot use SSL cipher suite selection as AES256.

[Workaround]



You can configure Windows cipher with following information http://support.microsoft.com/kb/980868/en-us

2. [SPR: 121203072]

[Symptom]

ext-group name and any password can login SSL VPN

# **System**

1. [SPR: 130207529]

[Symptom]

When change SSH, Telnet and FTP Service default port, the connect session still exist.

2. [SPR: 150529308]

[Symptom]

Console sometime dump XXX daemon dead message during rebooting.

# **Anti-Virus**

1. [SPR: 150522817]

[Symptom]

Upload Virus file by HTTP or Emails, the virus can be corrected detected and destroyed but the file name may be truncated in system log if the file name contains SPACE: '', SEMICOLON: ';' or DOUBLE-QUOTE: '"'.

2. [SPR: 150603299]

[Symptom]

Virus-infected mail sent via IMAP protocol cannot be detected effectively.

### Wireless

1. [SPR: 150701137]

[Symptom]

Try to manage too many external APs over service/license count may cause capwap\_srv daemon dead.



# Features: V4.13(AAKZ.1)C0

#### Modifications in V4.13(AAKZ.1)C0 - 2015/08/30

### 1. [BUGFIX]

Some objects cannot be correctly added or removed by CloudCNM.



# Features: V4.13(AAKZ.0)C0

### Modifications in V4.13(AAKZ.0)C0 - 2015/08/15

#### 1. [ENHANCEMENT]

Management Feature Enhancement:

- 1. Support CloudCNM, a cloud-based network management system. 4.13 CloudCNM feature support includes:
  - Batch import of managed devices at one time using one CSV file
  - See an overview of all managed devices and system information in one place
  - Monitor and manage devices
  - Install firmware to multiple devices of the same model at one time
  - Backup and restore device configuration
  - View the location of managed devices on a map
  - Receive notification for events and alarms, such as when a device goes down
  - Graphically monitor individual devices and see related statistics
  - Directly access a device for remote configuration
  - Create four types of administrators with different privileges
  - Perform Site-to-Site, Hub & Spoke, Fully-meshed and Remote Access VPN provisioning.
- 2. Support Russian Language
- 3. VPN MIB Support: eITS#150317956

SNMP VPN status MIBs.

The VPN status MIB is a MIB table containing the following information:

- Connection name
- VPN gateway
- IP version
- Active status
- Connected status.

Followings are the example of snmpwalk for the added MIBs;

VPN status MIB table:

- 1.3.6.1.4.1.890.1.6.22.2.4.1.1.1 = INTEGER: 1 --> table index
- 1.3.6.1.4.1.890.1.6.22.2.4.1.1.2 = INTEGER: 2
- 1.3.6.1.4.1.890.1.6.22.2.4.1.1.3 = INTEGER: 3
- 1.3.6.1.4.1.890.1.6.22.2.4.1.2.1 = STRING: "vpnconn1" --> name
- 1.3.6.1.4.1.890.1.6.22.2.4.1.2.2 = STRING: "vpnconn2"
- 1.3.6.1.4.1.890.1.6.22.2.4.1.2.3 = STRING: "vpn6conn1"
- 1.3.6.1.4.1.890.1.6.22.2.4.1.3.1 = STRING: "usg110\_1" --> gateway
- 1.3.6.1.4.1.890.1.6.22.2.4.1.3.2 = STRING: "usg110\_1"



- 1.3.6.1.4.1.890.1.6.22.2.4.1.3.3 = STRING: "vpn6\_1"
- 1.3.6.1.4.1.890.1.6.22.2.4.1.4.1 = STRING: "IPv4" --> IP version
- 1.3.6.1.4.1.890.1.6.22.2.4.1.4.2 = STRING: "IPv4"
- 1.3.6.1.4.1.890.1.6.22.2.4.1.4.3 = STRING: "IPv6"
- 1.3.6.1.4.1.890.1.6.22.2.4.1.5.1 = INTEGER: 0 --> active status
- 1.3.6.1.4.1.890.1.6.22.2.4.1.5.2 = INTEGER: 1
- 1.3.6.1.4.1.890.1.6.22.2.4.1.5.3 = INTEGER: 1
- 1.3.6.1.4.1.890.1.6.22.2.4.1.6.1 = INTEGER: 0 --> connected status
- 1.3.6.1.4.1.890.1.6.22.2.4.1.6.2 = INTEGER: 0
- 1.3.6.1.4.1.890.1.6.22.2.4.1.6.3 = INTEGER: 0

VPN connection counter MIBs.

The VPN connection counter MIB is a MIB group containing:

- Total VPN connection configured
- Number of activated connection
- Number of connected connection
- Number of disconnected connection

Followings are the example of snmpwalk for the added MIBs;

VPN connection counters:

- 1.3.6.1.4.1.890.1.6.22.2.5.1.0 = Counter32: 3 --> Total connection configured
- 1.3.6.1.4.1.890.1.6.22.2.5.2.0 = Counter32: 2 --> Number of active connection
- 1.3.6.1.4.1.890.1.6.22.2.5.3.0 = Counter32: 0 --> Number of connected connection
- 1.3.6.1.4.1.890.1.6.22.2.5.4.0 = Counter32: 2 --> Number of disconnected connection

MIB table for VPN SA monitor

The new OID is 1.3.6.1.4.1.890.1.6.22.2.6.

The MIB table contains the following columns:

- 1.3.6.1.4.1.890.1.6.22.2.6.1.1 --> VPN connection index
- 1.3.6.1.4.1.890.1.6.22.2.6.1.2 --> VPN connection name
- 1.3.6.1.4.1.890.1.6.22.2.6.1.3 --> VPN connection policy
- 1.3.6.1.4.1.890.1.6.22.2.6.1.4 --> VPN connection uptime
- 1.3.6.1.4.1.890.1.6.22.2.6.1.5 --> VPN connection timeout
- 1.3.6.1.4.1.890.1.6.22.2.6.1.6 --> Number of in-bound packets for the connection
- 1.3.6.1.4.1.890.1.6.22.2.6.1.7 --> Number of in-bound octets for the connection
- 1.3.6.1.4.1.890.1.6.22.2.6.1.8 --> Number of out-bound packets for the connection
- 1.3.6.1.4.1.890.1.6.22.2.6.1.9 --> Number of out-bound octets for the



connection

- 4. Support license refresh immediately while device-ha backup device become active.
- 5. Add pre-defined configuration (or pre-defined UTM profile) by default.
- 6. Offering DHCP option 138 has been disabled by default.

### 2. [ENHANCEMENT]

Connectivity Feature Enhancement:

- 1. Support RPS(Receive Packet Steering) to ensure that packets for the same stream of data are sent to the same CPU, which could help to increase performance in a congest(low bandwidth or high latency) network environment, eITS# 150200442, 150200636.
- 2. We enlarge static DHCP host pool from 512 to 1024 for ZyWALL 1100, USG1100, and USG1900, eITS# 150100773
- 3. Adjust Spec for SSLVPN Connections

Model	Default SSLVPN	Maximum SSLVPN
	Connections	Connections
USG40/40W	5	15
USG60/60W	5	20
USG110	25	150
USG210	35	150
USG310	50	150
USG1100	250	500
USG1900	250	750
ZyWALL 110	25	150
ZyWALL 310	50	150
ZyWALL 1100	250	500

#### 3. [ENHANCEMENT]

Security Feature Enhancement:

- 1. ADP engine and IDP engine upgrade to support more social networking application behavior, such as FACEBOOK like, FACEBOOK share...etc.
- 4. [ENHANCEMENT] eITS#150200756

UDP session timeout value can be configured up to 28800 seconds.

5. [ENHANCEMENT]

Patches for CVE-2015-0204, FREAK: OpenSSL vulnerability.

6. [ENHANCEMENT]

Patches for CVE-2015-4000, Logjam: TLS vulnerabilities (CVE-2015-4000).

7. [ENHANCEMENT]

Patches for vulnerability of HTTP authentication module which may cause USG behave as an open proxy to proxy HTTP request from external clients to internal servers.

8. [ENHANCEMENT]

Add CLI "no ip icmp-redirects" command to disable ICMP redirects manually.

9. [BUG FIX] eITS#150317956





[OID]OID formats are different between USG40W and USG1900.

[Condition]

MIBs...1.3.6.1.4.1.890.1.15.3.1.6.0.....

USG40W: V4.11(AALB.0)/1.01 | Aug 28 2013 14:19:07/2015-03-13 06:53:46

USG1900: V4.11(AAPL.0)/1.10/2015-03-13 01:27:44

## 10. [BUG FIX] eITS#150301008

DNS Security configuration can't change.

[Condition]

- 1. Go to Configuration > System > DNS > Click Show Advanced Settings > Security Option Control > Edit default profile e.g. Query Recursion deny > Click OK button
- 2. You will find the OK button no function.

# 11. [BUG FIX] eITS#150300062

If adding radius server into auth. method, L2TP cannot be established successfully. [Condition]

- 1. Go to Configuration > Object > AAA Server > RADIUS.
- 2. Set Server address: R1.domain.tw
- 3. Set Backup Server address: R2.domain.tw (PS. R1.domain.tw and R2.domain.tw need result same ip address)
- 4. Radiusd daemon couldn't bring on fail.

# 12. [BUG FIX] eITS#150300789

Combo-box show field is in wrong location.

[Condition]

- 1. In the settings of WLAN-interface, the input fields "802.11 band" and "Channel" are incorrectly positioned.
- 2. The problem occurs only in the browser IE 11

### 13. [BUG FIX] eITS#150300851

Limited admin user fails to view click diagnostic page

[Condition]

- 1. Add a limited admin account
- 2. Login by limited admin
- 3. Go to Maintenance > Diagnostic
- 4. You will find USG GUI no response

# 14. [BUG FIX] eITS#150300910

DHCP Relay may not work in Device HA environment.

[Condition]

When master device change status from fault state to active state, the DHCP relay function may not work.



15. [BUG FIX] eITS#150400012, 150200484, 150500302, 150600123, 150301005, 150501020, 150301061

In some cases, apply configuration will fail and cause zyshd dead. This may occur during the firmware upgrade progress or manually apply configuration.

#### 16. [BUG FIX] eITS#150400115

[SSO][Authentication] Without SSO enabled, user can be correctly authenticated and associated with the AD-group "Internet Users". However, with SSO enabled, the user from the AD-group "Internet Users" always appears only in the group of "ext-user (ad-users)".

#### 17. [BUG FIX] eITS#150301062

VLAN Packets can still be sent out even the base interface is disabled.

#### 18. [BUG FIX] eITS#150300850

Configure many static DHCP address up to maximum, the CLI command may not correctly be configured and cause "incomplete entry" error each time DUT reboot.

#### 19. [BUG FIX] eITS#150401185

In USG310, 1100, 1900, ZyWALL 310, 1100, it will show error message when configuring the port negotiation type on port 8.

#### 20. [BUG FIX] eITS#150400882

When trying to sort the table (Hits) of "Top 5 Viruses" and "Top 5 Intrusions" in Dashboard by descending/ascending, sorting is only by the first digit.

#### 21. [BUG FIX] eITS#150500769

Unable to edit application object page if it contains "," character.

22. [BUG FIX] eITS#150300799, 150400336, 150401001, 150401067, 150401143, 150200666 SSO does not work correctly sometimes.

#### 23. [BUG FIX] eITS#150300240

Unable to open IDP signature name to see the description in MONITOR > UTM Statistics > IDP

#### 24. [BUG FIX] eITS#150200331

Fix unexpected reboot related to packet processing.

#### 25. [BUG FIX] eITS#140900194, 150600194

In some cases, user cannot get mails from external mail server through USG.

#### 26. [BUG FIX] eITS#150200355

When we set speed on port1, the traffic doesn't work and show some abnormal message.

#### 27. [BUG FIX] eITS#150600082

The CF report in monitoring page and report server record not match.

28. [BUG FIX] eITS#150600688

In some cases, DUT will crash when trying to establish L2TP.

29. [BUG FIX] eITS#150501015



In some cases, enable connectivity check in policy route rules may cause zyshd daemon dead.

30. [BUG FIX] eITS#150600137

In some cases, AV signature cannot be successfully updated.

31. [BUG FIX] eITS#150700094

Self-Signed DSA certificate can be created but cannot show on the GUI.

#### 32. [BUG FIX] eITS#150300324

In USG110, USG210 and ZyWALL 110, DUT will become pure switch in a short period during booting process. When external AP and USG reboot at the same time, there might have possibility that AP will acquire IP address from outer DHCP server instead of DUT LAN DHCP server.

#### 33. [BUG FIX] eITS#150600585

Wrong German translation, "Intra-BSS-Verkehr aktivieren" should be corrected to "Intra-BSS-Verkehr blockieren"

34. [BUG FIX] eITS#150200663, 150500327

Some mails with attached files transferred from WAN to LAN cannot be received while Anti-Spam enabled.

#### 35. [BUG FIX] eITS#150100252

TFTP over IPsec cannot work well in the following topology.

```
TFTP Server------USG40/60=====VPN tunnel=====USG20-----TFTP Client
```

#### 36. [BUG FIX] eITS#150100898

After Device HA fallback to Master, IP on VLAN interface become 0.0.0.0.

37. [BUG FIX] eITS# 150500371

3G dongle E372 cannot work well in ZLD 4.11 Firmware.

#### 38. [BUG FIX] eITS# 150200205

Some session will hit wrong BWM rules with application service type and application object is not any.

39. [BUG FIX] eITS# 150200080

ZyXEL VPN Client cannot establish VPN tunnel when using DUT default certificate to do IKE authentication.

40. [BUG FIX] eITS# 141200576

Fix the issue that 'Disconnect Connections Before Falling Back' cannot work.

41. [BUG FIX] eITS# 140800138

When setting Email Daily Report, strange log "msg="/USR/SBIN/CRON: (root) MAIL (mailed 369 bytes of output but got status 0x0001)" will dump in system log.



# Features: V4.11(AAKZ.2)C0

### Modifications in V4.11(AAKZ.2)C0 - 2015/04/28

#### 1. [BUG FIX] eITS#150400012

Apply configuration which has SSID "VLAN Support" may causes zyshd daemon dead and device cannot be managed any more. User must reset device to default for recovery.



# Features: V4.11(AAKZ.1)C0

#### Modifications in V4.11(AAKZ.1)C0 - 2015/04/21

1. [BUG FIX] eITS#150301160

Content Filter doesn't work at all after 4.11 upgrade.

2. [BUG FIX] eITS#150200801

Radius daemon will fail to launch if the radius server (in AAA server) is configured with domain name and DNS is not ready during device boot-up.

3. [BUG FIX] eITS#150301005

When SSID "VLAN Support" has been enabled, device will fail to load start-up config after reboot. User must reset device to default for recovery.

# Features: V4.11(AAKZ.0)C0

#### Modifications in V4.11(AAKZ.0)C0 - 2015/03/12

1. [ENHANCEMENT]

Management feature enhancement:

- 1. ZON Utility Support (Device Discovery, Change Admin Password, Firmware Upgrade, Reboot Device, Web GUI Link)
- 2. Smart Connect Support (Device Discovery, Web GUI Link)

#### 2. [ENHANCEMENT]

Connectivity feature enhancement:

- 1. AP Controller Technology 1.9
- 2. LTE dongle support
- 3. VLAN 802.1P marking support

#### 3. [ENHANCEMENT]

Security feature enhancement:

- 1. Antivirus white/black list
- 2. Support ADP scan IPv6 traffic
- 3. ADP block time period
- 4. DNS security option control
- 5. SNMPv3
- 6. Add Reject Option in Security Policy
- 7. Add AV EICAR Detect Option
- 8. Add Action for untrusted cert chain of SSL Inspection
- 9. SSL Inspection certificate support cloud update.
- 10. UTM Performance Tuning #eITS141100375, 150100136, 150100251, 150200495

#### 4. [ENHANCEMENT]

Usability enhancement

- 1. Wireless Initial Installation Wizard
- 2. Network Diagnostic tools on GUI
- 3. Security Policy Rules Filter & Clone
- 4. UTM Profile Viewer
- 5. Policy Route Rule Filter
- 6. NAT rule support service group
- 7. Dual image enhancement
- 8. Multi-Lingual GUI

#### 5. [ENHANCEMENT]

VPN Feature Enhancement:

1. L2TP/IPsec behind NAT.



6. [ENHANCEMENT] eITS# 141100032

Certificate support space character in the following field: Organizational Unit, Organization, Town, State (Province), Country.

7. [ENHANCEMENT] eITS#141000153

Support GUI check box "Use Static-Dynamic Route to Control 1-1 NAT Route" to change routing order. Static-Dynamic Route has higher priority to 1-1 NAT Route when it is enabled.

8. [ENHANCEMENT]

Patches for CVE-2015-0235, GHOST Vulnerability of glibc.

#### 9. [FEATURE CHANGE] SPR#141007503

AP Controller default configuration changed from "Always Accept" to "Manual" setting.

10. [FEATURE CHANGE]

WAS:

AV, CF, AS black and white list and IDP custom signature **DO NOT** work without license.

IS:

AV, CF, AS black and white list and IDP custom signature **DO** work even without license.

#### 11. [FEATURE CHANGE]

Enlarge Log Entry Size by each model

WAS:

For USG110/210/310/ and ZyWALL110/310: 512

For USG1100/1900 and ZyWALL 1100: 512

#### IS:

For USG110/210/310/ and ZyWALL110/310: 1024

For USG1100/1900 and ZyWALL 1100: 2048

USG40/40W/60/60W keep log entry size as 512.

#### 12. [BUG FIX] eITS#150200052

Dynu DDNS cannot work

13. [BUG FIX] eITS#150100468, 140900136

Not connected to zyshd daemon due to deadlock by sshipsecpm connectivity check.

#### 14. [BUG FIX] eITS#141200823

DUT cannot connect to SSO agent and output CLI command as below:

Router# show sso agent status

% connect failed

% SSO: domain socket fial!

ZySSO Primary Agent: offline

ZySSO Secondary Agent: offline



#### 15. [BUG FIX] eITS#150100588

Apply configuration failed in the following steps:

- 1. reset the device back to default
- 2. Modify the WWW HTTPs port from 443 to 447, and some NAT and policy route rules.
- 3. Download the startup.conf which with HTTPs port as 447.
- 4. Change the startup.conf name as test\_www and upload it.
- 5. Apply test\_www config.
- 6. After device boot up, the device will fall back to default.

#### 16. [BUG FIX] eITS#141100503

Strange behavior when ZyWALL is in DNS proxy role.

[Condition]

- 1. Add zone forwarder 8.8.8.8 for zone \* via WAN interface
- 2. Add A-record for domain ftp.zanolari.net, IP 192.168.200.3
- 3. On PC, ping <u>www.zanolari.net</u>
- 4. Run CLI 'show ip dns server cache' and check www.zanolari.net is in DNS cache
- 5. Capture packets on device for WAN interface and port 53 (DNS)

6. On PC, run command 'ipconfig /flushdns' to flush DNS cache on PC, and then ping www.zanolari.net again

7. From captured packets you will find device sends DNS query for <u>www.zanolari.net</u> even if it is found in device's DNS cache.

#### 17. [BUG FIX] eITS#141200186, 150100084

After enabling AS, the throughput is low.

#### 18. [BUG FIX] eITS#141200341, 141200033

Move the log "App ID has been changed from 83886594 to 83886855" to debug log.

#### 19. [BUG FIX] eITS#141001029

User cannot be configured in security policy rule with zone to zone rule from WAN to ZyWALL.

#### 20. [BUG FIX] eITS#141100574

After rebooting, WAN gateway will disappear.

#### 21. [BUG FIX] eITS#141100745

Device's management IP cannot be reachable while Device HA status changed.

#### 22. [BUG FIX] eITS#141000415

The tunnel shows to be up in VPN Connections in both sides. However, no traffic can pass the tunnel and the log shows IPsec error with "no rule found, Dropping ESP packet".

#### 23. [BUG FIX] eITS#141100945

Device HA failed to synchronize backup device with master device.

24. [BUG FIX] eITS#141200132





The IP pool size cannot be varied with the changing of IP pool start address on GUI. [Condition]

- 1. Default "IP Address" is 192.168.1.1 and "IP Pool Start Address" is 192.168.1.33. The maximum pool size value is 223.
- 2. Change the "IP Pool Start Address" to 192.168.1.60, the pool size should be 196 but it is still 223.
- 25. [BUG FIX] eITS#141100753

Signature release date didn't display based on different time zone.

26. [BUG FIX] eITS#141100849

Changing the firewall rule to deny traffic to ZyWALL but not take effect immediately.

27. [BUG FIX] eITS#141100177

Building IPsec VPN tunnel with FortiGate, VPN tunnel cannot build after rekeying.

28. [BUG FIX] eITS#140800319

Download files may get stuck when UTM is activated.

29. [BUG FIX] eITS#141100097

Validation result of my certificate is failed.

30. [BUG FIX] eITS#141100402

Packets are sending out in the wrong interface.

31. [BUG FIX] eITS#141001052

Device has wrong or missing DNS cache record.

32. [BUG FIX] eITS#141000951

When using for SHA256 as intermediate certificate, the certificate path will shows "incomplete path".

33. [BUG FIX] eITS#141000870, 141100240

Rename a zone which has been used in Policy Control Rules will cause the zone field of these policy control rules cannot be changed or modified to other zones.

# 34. [BUG FIX] eITS#140900955

[RIP]When setting RIP redistribute OSPF as metric=3, reboot DUT will show error message and cause applying startup configuration failed.

# 35. [BUG FIX] eITS#140926122

[DHCPv6] When LAN interface set DHCPv6 client, it cannot send NS Packet.

# 36. [BUG FIX] eITS#140900251, SPR#140922847

[File Manager]Rename configuration file to 64 characters will fail with wrong CLI command.

37. [BUG FIX] eITS#141000516

[File Manager]Trying to download a file from download.microsoft.com or using the windows update service, in USG logs, IDP blocks the access

38. [BUG FIX] eITS#140900051



Route packets from a bridge interface according to the NAT result.

#### 39. [BUG FIX] eITS#140900272

Ge3 is configured as IP/MAC binding enabled. Disable interface any one of ge4 ~ ge8. The DHCP client of ge3 is unable to ping the default gateway anymore.

#### 40. [BUG FIX] eITS#141100569

[Interface] Routing didn't change even connective check failed.

### 41. [BUG FIX] eITS#150100603

IPsec VPN daemon causes high memory usage(99%).



# Features: V4.10(AAKZ.2)C0

## Modifications in V4.10(AAKZ.2)C0 - 2014/12/03

1. [ENHANCEMENT] eITS#140600094

Update driver to fix IOP issue with Genexis FiberXport device.

2. [ENHANCEMENT]

Add CLI to show the mapping for internal and external interface. CLI: "debug interface show mapping"

#### 3. [ENHANCEMENT] eITS#141000162

Change log format as following:

Before:

category="ipsec" level="error" src="" dst="" msg="Failed to send packet, err=N"N: 1 or 2

After:

category="ipsec" level="debug" src="<source and port of packet>" dst="<destination and port of packet>" msg="Packet(PROTOCOL) cannot be sent, reason: REASON"

PROTOCOL: ESP/AH/TCP/UDP/Unknown(protocol number)

REASON: System dropped/Network congestion/Traffic control dropped

4. [ENHANCEMENT]

Update bash binary for shellshock bash vulnerability issue

5. [ENHANCEMENT] eITS#140900846

Support Huawei E303 USB 3G dongle with version 22.318.27.00.00

6. [ENHANCEMENT]

Add SNMP VPN status and connection counter MIBs.

The VPN status MIB is a MIB table containing the following information:

Connection name, VPN gateway, IP version, active status, and connected status.

The VPN connection counter is a MIB group containing:

Total VPN connection configured, number of activated connection, number of connected connection, and number disconnected connection.

Followings are the example of snmpwalk for the added MIBs;

VPN status MIB table:

1.3.6.1.4.1.890.1.6.22.2.4.1.1.1 = INTEGER: 1 --> table index

- 1.3.6.1.4.1.890.1.6.22.2.4.1.1.2 = INTEGER: 2
- 1.3.6.1.4.1.890.1.6.22.2.4.1.1.3 = INTEGER: 3
- 1.3.6.1.4.1.890.1.6.22.2.4.1.2.1 = STRING: ""vpnconn1"" --> name

1.3.6.1.4.1.890.1.6.22.2.4.1.2.2 = STRING: ""vpnconn2""

1.3.6.1.4.1.890.1.6.22.2.4.1.2.3 = STRING: ""vpn6conn1""

1.3.6.1.4.1.890.1.6.22.2.4.1.3.1 = STRING: ""usg110\_1"" --> gateway



1.3.6.1.4.1.890.1.6.22.2.4.1.3.2 = STRING: ""usg110\_1"" 1.3.6.1.4.1.890.1.6.22.2.4.1.3.3 = STRING: ""vpn6\_1"" 1.3.6.1.4.1.890.1.6.22.2.4.1.4.1 = STRING: ""IPv4"" --> IP version 1.3.6.1.4.1.890.1.6.22.2.4.1.4.2 = STRING: ""IPv4"" 1.3.6.1.4.1.890.1.6.22.2.4.1.4.3 = STRING: ""IPv6"" 1.3.6.1.4.1.890.1.6.22.2.4.1.5.1 = INTEGER: 0 --> active status 1.3.6.1.4.1.890.1.6.22.2.4.1.5.2 = INTEGER: 1 1.3.6.1.4.1.890.1.6.22.2.4.1.5.3 = INTEGER: 1 1.3.6.1.4.1.890.1.6.22.2.4.1.6.1 = INTEGER: 0 --> connected status 1.3.6.1.4.1.890.1.6.22.2.4.1.6.2 = INTEGER: 0 1.3.6.1.4.1.890.1.6.22.2.4.1.6.3 = INTEGER: 0

VPN connection counters:

1.3.6.1.4.1.890.1.6.22.2.5.1.0 = Counter32: 3 --> total connection configured

1.3.6.1.4.1.890.1.6.22.2.5.2.0 = Counter32: 2 --> number of active connection

1.3.6.1.4.1.890.1.6.22.2.5.3.0 = Counter32: 0 --> number of connected connection

```
1.3.6.1.4.1.890.1.6.22.2.5.4.0 = Counter32: 2 --> number of disconnected connection
```

The number of disconnected connection is equal to the number of active connection minus the number of connected connection"

7. [ENHANCEMENT] eITS#140800801, 141000157

Improve SMB performance

8. [ENHANCEMENT] eITS#141000576

PPTP ALG support server in LAN scenario

9. [ENHANCEMENT]

Add an interface at GUI to setting SSL Inspection policy for untrusted certificate chain

#### 10. [ENHANCEMENT]

Single Sign-on support authentication failover to web authentication. Note: With SSO Agent 1.0.4 or above.

[Condition]

When enable both Single Sign-on and Force User Authentication in web authentication policy. Once the Single Sign-On authentication fail, user will be redirect to web authentication login page as second authentication method.

#### 11. [FEATURE CHANGE] eITS#141000788

Turn off SSLV3 support in build-in service(HTTPs) by default due to Poodle vulnerability issue

12. [FEATURE CHANGE] eITS#141000154

WAS: The columns "IKE Name" and "Cookies" showed on VPN Monitor

IS: The columns "IKE Name" and "Cookies" are hidden on VPN Monitor by default.

13. [FEATURE CHANGE]



WAS: WLAN bind with lan1 by default

IS: WLAN bind with lan2 by default

14. [FEATURE CHANGE]

WAS:

Log entry is 256

IS:

Log entry is 512

PS: For ZyWALL 310 and USG310 only

15. [FEATURE CHANGE]

WAS:

IKE packet can be sent from any interface by routing even the packet's source IP doesn't match to the outgoing interface.

IS:

The IKE packet can only be sent from the interface bound the same IP with the packet's source IP. The above feature may cause some scenario of VPN establishment not work. Please refer to KB:

http://kb.zyxel.com/KB/searchArticle!viewDetail.action?articleOid=014363&lang=EN

#### 16. [BUG FIX] eITS#140900194

User cannot get mail from external mail server through USG due to duplicate ACK packet.

17. [BUG FIX] eITS#140800834

USG with wrong CEF syslog format

18. [BUG FIX] eITS#140800642

Device HA status not changed when monitored interface IP changed

19. [BUG FIX] eITS#141000158

SSLVPN reverse proxy RDP cannot work

20. [BUG FIX] eITS#140900380

USG1100 / L2TP can't login user and with crazy log message

21. [BUG FIX] eITS#141000460, 141000461, 141000462

Static ARP entry will gone if enabling device HA

22. [BUG FIX] eITS#141000171

USG boot up makes switch function("Loop Guard") blocking port

23. [BUG FIX] eITS#141000157

False alarm in CAPWAP protocol in ADP engine

24. [BUG FIX] eITS#141000155

IKE packet sent at wrong interface and wrong IP

25. [BUG FIX] eITS#141000458

DHCP will clear static ARP entry after send DHCP ACK

26. [BUG FIX] eITS#141001108

# **ZyXEL**

#### www.zyxel.com

USG110 cannot load Firmware if USB memory stick connected

27. [BUG FIX] eITS#140800642, SPR#140714684, 140804120, 141103007

ZyWALL 1100 - VPN connect fail and hang

28. [BUG FIX] eITS#140700610, 141000163, SPR#140909287

After device boot up, the log will show that the DHCP packets have been dropped by default firewall rule. However, WAN interface still gets the IP address from DHCP server.



# Features: V4.10(AAKZ.1)C0

### Modifications in V4.10(AAKZ.1)C0 - 2014/10/01

Release for manufacturing



# Features: V4.10(AAKZ.0)C0

Modifications in V4.10(AAKZ.0)C0 - 2014/08/22

First release



#### **Appendix 1. Firmware upgrade / downgrade procedure**

The following is the firmware **upgrade** procedure:

- 1. If user did not backup the configuration file before firmware upgrade, please follow the procedures below:
  - Use Browser to login into ZyWALL/USG as administrator.
  - Click Maintenance > File Manager > Configuration File to open the Configuration File Screen. Use the Configuration File screen to backup current configuration file.
  - Find firmware at www.zyxel.com in a file that (usually) uses the system model name with a .bin extension, for example, "413AAKZ1C0.bin".
  - Click Maintenance > File Manager > Firmware Package to open the Firmware Package Screen. Browser to the location of firmware package and then click Upload. The ZyWALL/USG automatically reboots after a successful upload.
  - After several minutes, the system is successfully upgraded to newest version.

The following is the firmware **downgrade** procedure:

- 1. If user has already backup the configuration file before firmware upgrade, please follow the procedures below:
  - Use Console/Telnet/SSH to login into ZyWALL/USG.
  - Router>enable\
  - Router#configure terminal
  - Router(config)#setenv-startup stop-on-error off
  - Router(config)#write
  - Load the older firmware to ZyWALL/USG using standard firmware upload procedure.
  - After system uploads and boot-up successfully, login into ZyWALL/USG via GUI.
  - Go to GUI → "File Manager" menu, select the backup configuration filename, for example, statup-config-backup.conf and press "Apply" button.
  - After several minutes, the system is successfully downgraded to older version.
- 2. If user did not backup the configuration file before firmware upgrade, please follow the procedures below:
  - Use Console/Telnet/SSH to login into ZyWALL/USG.
  - Router>enable
  - Router#configure terminal
  - Router(config)#setenv-startup stop-on-error off
  - Router(config)#write
  - Load the older firmware to ZyWALL/USG using standard firmware upload procedure.
  - After system upload and boot-up successfully, login into ZyWALL/USG via Console/Telnet/SSH.
  - Router>enable
  - Router#write

Now the system is successfully downgraded to older version.

Note: ZyWALL/USG might lose some configuration settings during this downgrade procedure. It is caused by configuration conflict between older and newer firmware version. If this situation happens, user needs to configure these settings again.



# Appendix 2. SNMPv2 private MIBS support

SNMPv2 private MIBs provides user to monitor ZyWALL/USG platform status. If user wants to use this feature, you must prepare the following step:

- 1. Have ZyWALL/USG mib files (**413AAKZ1C0-enterprise.mib** and **413AAKZ1C0private.mib**) and install to your MIBs application (like MIB-browser). You can see 410AAPJ2C0-private.mib (OLD is 1.3.6.1.4.1.890.1.6.22).
- 2. ZyWALL/USG SNMP is enabled.
- 3. Using your MIBs application connects to ZyWALL/USG.
- 4. SNMPv2 private MIBs support three kinds of status in ZyWALL/USG:
  - 1. CPU usage: Device CPU loading (%)
  - 2. Memory usage: Device RAM usage (%)
  - 3. VPNIpsecTotalThroughput: The VPN total throughput (Bytes/s), Total means all packets (Tx + Rx) through VPN.



#### **Appendix 3. Firmware Recovery**

In some rare situation(symptom as following), ZyWALL/USG might not boot up successfully after firmware upgrade. The following procedures are the steps to recover firmware to normal condition. Please connect console cable to ZyWALL/USG.

- 1. Symptom:
  - Booting success but device show error message "can't get kernel image" while device boot.
     U-Boot 2011.03 (Development build, synversion: u-boot:422M, exec:exported) (Build time: Feb 21 2013 - 10:15:57)

```
BootModule Version: V1.07 | 02/21/2013 10:45:46
DRAM: Size = 2048 Mbytes
Press any key to enter debug mode within 3 seconds.
Wrong Image Format for bootm command
ERROR: can't get kernel image!
Start to check file system...
```

• Device reboot infinitely.

```
U-Boot 2011.03 (Development build, svnversion: u-boot:422M, exec:exported)
(Build time: Feb 21 2013 - 10:15:57)
```


```
BootModule Version: V1.07 | 02/21/2013 10:45:46
DRAM: Size = 2048 Mbytes
```

```
Press any key to enter debug mode within 3 seconds.
.....
U-Boot 2011.03 (Development build, svnversion: u-boot:422M, exec:exported)
(Build time: Feb 21 2013 - 10:15:57)
```

```
BootModule Version: V1.07 | 02/21/2013 10:45:46
DRAM: Size = 2048 Mbytes
```

Press any key to enter debug mode within 3 seconds.

• Nothing displays after "Press any key to enter debug mode within 3 seconds." for more than1 minute.



• Startup message displays "Invalid Recovery Image".




U-Boot 2011.03 (Development build, svnversion: u-boot:422M, exec:exported) (Build time: Feb 21 2013 - 10:15:57) BootModule Version: V1.07 | 02/21/2013 10:45:46 DRAM: Size = 2048 Mbytes Press any key to enter debug mode within 3 seconds. ..... Invalid Recovery Image ERROR EnterDebug Mode ZW1100> • The message here could be "Invalid Firmware". However, it is equivalent to "Invalid

• The message here could be "Invalid Filmware". However, it is equivalent Recovery Image".

Invalid Firmware!!! ERROR

#### 2. Recover steps

• Press any key to enter debug mode



> atkz -f -l 192.168.1.1

• Enter atgof to bring up the FTP server on port 1

ZyWALL 1100> atgof

Booting...


• The following information shows the FTP service is up and ready to receive FW Building ....

Connect a computer to port 1 and FTP to 192.168.1.1 to upload the new file.

• You will use FTP to upload the firmware package. Keep the console session open in order to see when the firmware update finishes.



- Set your computer to use a static IP address from 192.168.1.2 ~ 192.168.1.254. No matter how you have configured the ZyWALL/USG's IP addresses, your computer must use a static IP address in this range to recover the firmware.
- Connect your computer to the ZyWALL/USG's port 1 (the only port that you can use for recovering the firmware).
- Use an FTP client on your computer to connect to the ZyWALL/USG. This example uses the ftp command in the Windows command prompt. The ZyWALL/USG's FTP server IP address for firmware recovery is 192.168.1.1
- Log in without user name (just press enter).
- Set the transfer mode to binary. Use "bin" (or just "bi" in the Windows command prompt).
- Transfer the firmware file from your computer to the ZyWALL/USG (the command is "put 310AAAC0C0.bin" in the Windows command prompt).



• The console session displays "Firmware received" after the FTP file transfer is complete. Then you need to wait while the ZyWALL/USG recovers the firmware (this may take up to 4 minutes).

Firmware received ...

[Update Filesystem] Updating Code

• The message here might be "ZLD-current received". Actually, it is equivalent to "Firmware received".

```
ZLD-current received ...
[Update Filesystem]
```

Updating Code

• The console session displays "done" when the firmware recovery is complete. Then the ZyWALL/USG automatically restarts.

ZyXEL www.zyxel.com done [Update Kernel] Extracting Kernel Image done Writing Kernel Image ... done Restarting system. • The username prompt displays after the ZyWALL/USG starts up successfully. The firmware recovery process is now complete and the ZyWALL/USG is ready to use. U-Boot 2011.03 (Development build, svnversion: u-boot:422M, exec:exported) (Build time: Feb 21 2013 - 10:15:57) BootModule Version: V1.07 | 02/21/2013 10:45:46 DRAM: Size = 2048 Mbytes Press any key to enter debug mode within 3 seconds. Start to check file system... /dev/sda3: 33/20480 files (0.0% non-contiguous), 57481/81920 blocks /dev/sda4: 97/23040 files (1.0% non-contiguous), 7623/92160 blocks Done INIT: version 2.86 booting Initializing Debug Account Authentication Seed (DAAS)... done. Setting the System Clock using the Hardware Clock as reference...System Cl ock set. Local time: Tue May 28 08:54:07 GMT 2013 INIT: Entering runlevel: 3 Starting zylog daemon: zylogd zylog starts. Starting zylog daemon. zyloga zylog odarie Starting syslog-ng. Starting ZLD Wrapper Daemon.... Starting uam daemon. Starting periodic command scheduler: cron. Start ZyWALL system daemon.... Got LINK\_CHANGE Got LINK\_CHANGE Port [1] Copper is up --> Group [1] is up .....Applying system configuration file, please wait.. no startup-config.conf file, Applying system-default.conf Use system default configuration file (system-default.conf) ZyWALL system is configured successfully with system-default.conf Welcome to ZyWALL 1100 Username:

- If one of the following cases occurs, you need to do the "firmware recovery process" again. Note that if the process is done several time but the problem remains, please collect all the console logs and send to ZyXEL/USG for further analysis.
  - One of the following messages appears on console, the process must be performed again ./bin/sh: /etc/zyxel/conf/ZLDconfig: No such file Error: no system default configuration file, system configuration stop!!