

Schweitzer Engineering Laboratories, Inc.

2350 NE Hopkins Court • Pullman, WA 99163-5603 USA Phone: +1.509.332.1890 • Fax: +1.509.332.7990 www.selinc.com • info@selinc.com

The FCC ID and warning are placed on a label on the side of the device as proposed. Per eCFR 2.925(d) and 2.925(d)(1), the ID and warning are printed on laminated labels and attached to the enclosure with a permanent adhesive.



Figure 1: WALL MOUNT, SIDE OF DEVICE



Schweitzer Engineering Laboratories, Inc. 2350 NE Hopkins Court • Pullman, WA 99163-5603 USA Phone: +1.509.332.1890 • Fax: +1.509.332.7990 www.selinc.com • info@selinc.com



Figure 2: WALL MOUNT, BACK OF DEVICE