







OBWac40 5190MHz Ant1






OBWac40 5230MHz Ant1



















































5 Maximum Power Spectral Density Level

5.1 Test Result

Mode	Frequency (MHz)	Antenna	Conducted PSD (dBm)	Duty Factor (dB)	Total PSD (dBm)	Limit (dBm)	Verdict
a	5180	Ant0	6.03	0.61	6.64	11	Pass
a	5200	Ant0	6.74	0.61	7.35	11	Pass
a	5240	Ant0	6.18	0.62	6.8	11	Pass
a	5260	Ant0	3.99	0.62	4.61	11	Pass
a	5280	Ant0	3.92	0.62	4.54	11	Pass
a	5320	Ant0	5.28	0.62	5.9	11	Pass
a	5500	Ant0	-7.62	0.62	-7.0	11	Pass
a	5600	Ant0	1.95	0.61	2.56	11	Pass
a	5700	Ant0	3.22	0.62	3.84	11	Pass
a	5180	Ant1	4.29	0.71	5	11	Pass
a	5200	Ant1	2.96	0.61	3.57	11	Pass
a	5240	Ant1	2.11	0.62	2.73	11	Pass
a	5260	Ant1	2.47	0.61	3.08	11	Pass
a	5280	Ant1	2.91	0.61	3.52	11	Pass
a	5320	Ant1	4.79	0.61	5.4	11	Pass
a	5500	Ant1	6.96	0.62	7.58	11	Pass
a	5600	Ant1	6.87	0.61	7.48	11	Pass
a	5700	Ant1	7.22	0.62	7.84	11	Pass
a	5180	Sum	--	--	8.907	10.13	Pass
a	5200	Sum	--	--	8.869	10.13	Pass
a	5240	Sum	--	--	8.236	10.13	Pass
a	5260	Sum	--	--	6.922	10.13	Pass
a	5280	Sum	--	--	7.070	10.13	Pass
a	5320	Sum	--	--	8.667	10.13	Pass
a	5500	Sum	--	--	7.729	10.13	Pass
a	5600	Sum	--	--	8.693	10.13	Pass
a	5700	Sum	--	--	9.295	10.13	Pass
n20	5180	Ant0	4.2	0.66	4.86	11	Pass
n20	5180	Ant1	2.59	0.65	3.24	11	Pass
n20	5180	Sum	--	--	7.135	10.13	Pass
n20	5200	Ant0	5.16	0.66	5.82	11	Pass
n20	5200	Ant1	1.74	0.66	2.4	11	Pass
n20	5200	Sum	--	--	7.449	10.13	Pass
n20	5240	Ant0	3.41	0.66	4.07	11	Pass
n20	5240	Ant1	2.24	0.66	2.9	11	Pass



n20	5240	Sum	--	--	6.535	10.13	Pass
n20	5280	Ant0	3.11	0.66	3.77	11	Pass
n20	5280	Ant1	2.3	0.66	2.96	11	Pass
n20	5280	Sum	--	--	6.394	10.13	Pass
n20	5320	Ant0	4.26	0.66	4.92	11	Pass
n20	5320	Ant1	3.1	0.66	3.76	11	Pass
n20	5320	Sum	--	--	7.389	10.13	Pass
n20	5500	Ant0	4.15	0.66	4.81	11	Pass
n20	5500	Ant1	6.71	0.66	7.37	11	Pass
n20	5500	Sum	--	--	9.286	10.13	Pass
n20	5600	Ant0	1.77	0.65	2.42	11	Pass
n20	5600	Ant1	6.07	0.65	6.72	11	Pass
n20	5600	Sum	--	--	8.092	10.13	Pass
n20	5700	Ant0	1.65	0.66	2.31	11	Pass
n20	5700	Ant1	6.67	0.65	7.32	11	Pass
n20	5700	Sum	--	--	8.511	10.13	Pass
n40	5190	Ant0	2.45	2.84	5.29	11	Pass
n40	5190	Ant1	-0.68	3.01	2.33	11	Pass
n40	5190	Sum	--	--	7.068	10.13	Pass
n40	5230	Ant0	2.85	2.83	5.68	11	Pass
n40	5230	Ant1	-0.88	3.23	2.35	11	Pass
n40	5230	Sum	--	--	7.337	10.13	Pass
n40	5270	Ant0	0.26	2.83	3.09	11	Pass
n40	5270	Ant1	-0.9	3.02	2.12	11	Pass
n40	5270	Sum	--	--	5.642	10.13	Pass
n40	5310	Ant0	2.75	2.84	5.59	11	Pass
n40	5310	Ant1	0.97	3.23	4.2	11	Pass
n40	5310	Sum	--	--	7.961	10.13	Pass
n40	5510	Ant0	0.96	2.83	3.79	11	Pass
n40	5510	Ant1	3.7	3.01	6.71	11	Pass
n40	5510	Sum	--	--	8.501	10.13	Pass
n40	5670	Ant0	-0.29	2.97	2.68	11	Pass
n40	5670	Ant1	3.8	3	6.8	11	Pass
n40	5670	Sum	--	--	8.222	10.13	Pass
ac20	5180	Ant0	4.4	1.16	5.56	11	Pass
ac20	5180	Ant1	2.21	1.17	3.38	11	Pass
ac20	5180	Sum	--	--	7.616	10.13	Pass
ac20	5200	Ant0	4.55	1.32	5.87	11	Pass
ac20	5200	Ant1	1.15	1.18	2.33	11	Pass
ac20	5200	Sum	--	--	7.461	10.13	Pass
ac20	5240	Ant0	4.27	1.17	5.44	11	Pass
ac20	5240	Ant1	1.65	1.17	2.82	11	Pass
ac20	5240	Sum	--	--	7.335	10.13	Pass



ac20	5280	Ant0	3.83	1.17	5	11	Pass
ac20	5280	Ant1	1.71	1.17	2.88	11	Pass
ac20	5280	Sum	--	--	7.078	10.13	Pass
ac20	5320	Ant0	4.55	1.17	5.72	11	Pass
ac20	5320	Ant1	2.3	1.17	3.47	11	Pass
ac20	5320	Sum	--	--	7.749	10.13	Pass
ac20	5500	Ant0	3.68	1.17	4.85	11	Pass
ac20	5500	Ant1	7.36	1.16	8.52	11	Pass
ac20	5500	Sum	--	--	10.072	10.13	Pass
ac20	5600	Ant0	0.99	1.17	2.16	11	Pass
ac20	5600	Ant1	7.37	1.17	8.54	11	Pass
ac20	5600	Sum	--	--	9.440	10.13	Pass
ac20	5700	Ant0	1.56	1.17	2.73	11	Pass
ac20	5700	Ant1	6.04	1.17	7.21	11	Pass
ac20	5700	Sum	--	--	8.534	10.13	Pass
ac40	5190	Ant0	1.14	3.37	4.51	11	Pass
ac40	5190	Ant1	0.33	3.69	4.02	11	Pass
ac40	5190	Sum	--	--	7.282	10.13	Pass
ac40	5230	Ant0	0.81	3.35	4.16	11	Pass
ac40	5230	Ant1	0.45	3.67	4.12	11	Pass
ac40	5230	Sum	--	--	7.150	10.13	Pass
ac40	5270	Ant0	0.68	3.37	4.05	11	Pass
ac40	5270	Ant1	-0.78	3.68	2.9	11	Pass
ac40	5270	Sum	--	--	6.523	10.13	Pass
ac40	5310	Ant0	1.22	3.37	4.59	11	Pass
ac40	5310	Ant1	-0.37	3.69	3.32	11	Pass
ac40	5310	Sum	--	--	7.012	10.13	Pass
ac40	5510	Ant0	2.25	3.35	5.6	11	Pass
ac40	5510	Ant1	3.15	3.6	6.75	11	Pass
ac40	5510	Sum	--	--	9.223	10.13	Pass
ac40	5670	Ant0	-0.36	3.38	3.02	11	Pass
ac40	5670	Ant1	2	3.63	5.63	11	Pass
ac40	5670	Sum	--	--	7.528	10.13	Pass
ac80	5210	Ant0	-1.07	4.17	3.1	11	Pass
ac80	5210	Ant1	-3.96	4.17	0.21	11	Pass
ac80	5210	Sum	--	--	4.901	10.13	Pass
ac80	5290	Ant0	-2.49	3.94	1.45	11	Pass
ac80	5290	Ant1	-2.82	3.94	1.12	11	Pass
ac80	5290	Sum	--	--	4.298	10.13	Pass
ac80	5530	Ant0	-2.07	3.92	1.85	11	Pass
ac80	5530	Ant1	1.73	3.92	5.65	11	Pass
ac80	5530	Sum	--	--	7.163	10.13	Pass
ac80	5610	Ant0	-5.52	4.27	-1.25	11	Pass




ac80	5610	Ant1	-0.85	3.81	2.96	11	Pass
ac80	5610	Sum	--	--	4.357	10.13	Pass
ax20	5180	Ant0	1.55	2.74	4.29	11	Pass
ax20	5180	Ant1	1.36	2.74	4.1	11	Pass
ax20	5180	Sum	--	--	7.206	10.13	Pass
ax20	5200	Ant0	3.02	2.75	5.77	11	Pass
ax20	5200	Ant1	0.78	2.74	3.52	11	Pass
ax20	5200	Sum	--	--	7.799	10.13	Pass
ax20	5240	Ant0	3.26	2.75	6.01	11	Pass
ax20	5240	Ant1	-0.02	2.74	2.72	11	Pass
ax20	5240	Sum	--	--	7.680	10.13	Pass
ax20	5280	Ant0	1.95	2.75	4.7	11	Pass
ax20	5280	Ant1	1.81	2.75	4.56	11	Pass
ax20	5280	Sum	--	--	7.641	10.13	Pass
ax20	5320	Ant0	5.57	2.74	8.31	11	Pass
ax20	5320	Ant1	1.65	2.75	4.4	11	Pass
ax20	5320	Sum	--	--	9.791	10.13	Pass
ax20	5500	Ant0	4.51	2.73	7.24	11	Pass
ax20	5500	Ant1	4.51	2.9	7.41	11	Pass
ax20	5500	Sum	--	--	10.336	10.13	Pass
ax20	5600	Ant0	0.88	2.75	3.63	11	Pass
ax20	5600	Ant1	5.74	2.75	8.49	11	Pass
ax20	5600	Sum	--	--	9.717	10.13	Pass
ax20	5700	Ant0	1.02	2.74	3.76	11	Pass
ax20	5700	Ant1	5.24	2.75	7.99	11	Pass
ax20	5700	Sum	--	--	9.381	10.13	Pass
ax40	5190	Ant0	1.32	2.82	4.14	11	Pass
ax40	5190	Ant1	-0.95	2.98	2.03	11	Pass
ax40	5190	Sum	--	--	6.222	10.13	Pass
ax40	5230	Ant0	0.11	2.82	2.93	11	Pass
ax40	5230	Ant1	-3.76	2.98	-0.78	11	Pass
ax40	5230	Sum	--	--	4.470	10.13	Pass
ax40	5270	Ant0	-0.62	2.82	2.2	11	Pass
ax40	5270	Ant1	-2.38	3.04	0.66	11	Pass
ax40	5270	Sum	--	--	4.508	10.13	Pass
ax40	5310	Ant0	-0.04	2.83	2.79	11	Pass
ax40	5310	Ant1	-1.27	2.97	1.7	11	Pass
ax40	5310	Sum	--	--	5.289	10.13	Pass
ax40	5510	Ant0	0.17	2.82	2.99	11	Pass
ax40	5510	Ant1	1.42	2.99	4.41	11	Pass
ax40	5510	Sum	--	--	6.768	10.13	Pass
ax40	5670	Ant0	-1.63	2.82	1.19	11	Pass
ax40	5670	Ant1	0.64	2.99	3.63	11	Pass






ax40	5670	Sum	--	--	5.589	10.13	Pass
ax80	5210	Ant0	-2.42	3.29	0.87	11	Pass
ax80	5210	Ant1	-5.19	3.59	-1.6	11	Pass
ax80	5210	Sum	--	--	2.819	10.13	Pass
ax80	5290	Ant0	-4.29	3.45	-0.84	11	Pass
ax80	5290	Ant1	-4.78	3.59	-1.19	11	Pass
ax80	5290	Sum	--	--	1.999	10.13	Pass
ax80	5530	Ant0	-3.32	3.46	0.14	11	Pass
ax80	5530	Ant1	-0.02	3.42	3.4	11	Pass
ax80	5530	Sum	--	--	5.079	10.13	Pass
ax80	5610	Ant0	-6.3	3.46	-2.84	11	Pass
ax80	5610	Ant1	-0.79	3.28	2.49	11	Pass
ax80	5610	Sum	--	--	3.606	10.13	Pass






5.2 Test Graphs

















































PSD n20 5700MHz Ant0
























PSDn40 5270MHz Ant0




PSD n40 5310MHz Ant0









PSD n40 5270MHz Ant1





PSD n40 5310MHz Ant1




PSDn40 5510MHz Ant1




PSD n40 5670MHz Ant1







PSD ac20 5240MHz Ant0






PSD ac20 5260MHz Ant0




PSD ac20 5280MHz Ant0











PSD ac20 5700MHz Ant0

































PSD ac40 5270MHz Ant1







PSD ac40 5310MHz Ant1























































































6 Frequency Stability

6.1 Test Result

Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
20C 102V	a	5180	Ant0	5180	0	0	25	Pass
20C 120V	a	5180	Ant0	5180	0	0	25	Pass
20C 138V	a	5180	Ant0	5180	0	0	25	Pass
-20C 120V	a	5180	Ant0	5180	0	0	25	Pass
-10C 120V	a	5180	Ant0	5180	0	0	25	Pass
0C 120V	a	5180	Ant0	5180	0	0	25	Pass
10C 120V	a	5180	Ant0	5180	0	0	25	Pass
30C 120V	a	5180	Ant0	5180	0	0	25	Pass
40C 120V	a	5180	Ant0	5180	0	0	25	Pass
50C 120V	a	5180	Ant0	5179.98	-20000	-3.86	25	Pass
20C 102V	a	5200	Ant0	5200	0	0	25	Pass
20C 120V	a	5200	Ant0	5200	0	0	25	Pass
20C 138V	a	5200	Ant0	5200.02	20000	3.85	25	Pass
-20C 120V	a	5200	Ant0	5199.98	-20000	-3.85	25	Pass
-10C 120V	a	5200	Ant0	5200.02	20000	3.85	25	Pass
0C 120V	a	5200	Ant0	5200	0	0	25	Pass
10C 120V	a	5200	Ant0	5200	0	0	25	Pass
30C 120V	a	5200	Ant0	5200.02	20000	3.85	25	Pass
40C 120V	a	5200	Ant0	5200.02	20000	3.85	25	Pass
20C 102V	a	5200	Ant0	5200	0	0	25	Pass
20C 102V	a	5240	Ant0	5240.02	20000	3.82	25	Pass
20C 120V	a	5240	Ant0	5240.02	20000	3.82	25	Pass
20C 138V	a	5240	Ant0	5239.98	-20000	-3.82	25	Pass
-20C 120V	a	5240	Ant0	5240	0	0	25	Pass
-10C 120V	a	5240	Ant0	5240.02	20000	3.82	25	Pass
0C 120V	a	5240	Ant0	5240.02	20000	3.82	25	Pass
10C 120V	a	5240	Ant0	5240.02	20000	3.82	25	Pass
30C 120V	a	5240	Ant0	5240	0	0	25	Pass
40C 120V	a	5240	Ant0	5240	0	0	25	Pass
50C 120V	a	5240	Ant0	5240.02	20000	3.82	25	Pass
20C 102V	a	5260	Ant0	5260	0	0	25	Pass
20C 120V	a	5260	Ant0	5260	0	0	25	Pass
20C 138V	a	5260	Ant0	5260	0	0	25	Pass
-20C 120V	a	5260	Ant0	5260.02	20000	3.8	25	Pass
-10C 120V	a	5260	Ant0	5260	0	0	25	Pass
0C 120V	a	5260	Ant0	5260	0	0	25	Pass