



# Intertek Testing Services

## ETL SEMKO

Report No.: 02150341  
Talk Mode

Tested By: Hong, Report No.: 02150341


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s  
Subranges: 16  
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698





# Intertek Testing Services

ETL SEMKO

Report No.: 02150341  
Talk Mode

Tested By: Hong, Report No.: 02150341

### Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

### Final Measurement

no Results