

Friedrich Air Conditioning Co.  
4200 N. PanExpressway  
P.O. Box 1540  
San Antonio, Texas 78295  
210-357-4400  
(Fax) 210-357-4480

6/9/2008

## 2008 CP10E10 and CP12E10 Shipping Block Removal

All 2008 CP10E10 and CP12E10 models are shipped with a protective shipping block adhered to the accumulator of the unit. The shipping block is designed to protect the unit from damage during the shipping process.

It is important that the shipping block be removed prior to operating the unit. Failure to remove the block may result in improper operation or damage to the unit.

The photo below shows the location of the shipping block.



We are making revisions to the installation manual to point out this step more clearly.