

To: Wilson Loke, Intertek Testing Services Hong Kong Ltd.
teama@itslabtest.com
From: Linda Elliott
lelliott@fcc.gov
FCC Equipment Authorization Branch

Re: FCC ID LBBMG5000

Applicant: Continental Conair Limited
Correspondence Reference Number: 16252
731 Confirmation Number: EA98716
Date of Original E-Mail: 9/21/2000

Subject:

An error occurred during the label document transmission, and the exhibit can not be viewed. Please re-submit the identification label. Sorry for any inconvenience this may cause you.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal pursuant to Section 2.917(c) and forfeiture of the filing fee pursuant to Section 1.1108

DO NOT Reply to this email by using the Reply button. In order for your response to be processed expeditiously, you must upload your response via the Internet at www.fcc.gov, E-Filing, OET Equipment Authorization Electronic Filing. If the response is submitted through Add Attachments, a message which informs the processing staff that a new exhibit has been submitted must also be submitted via Submit Correspondence. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.