



# Label Information

## 1. Label drawing

<p>Part No. : 96560 R5720 Model : ATC32HYAN</p> <p>HW ver : 0</p> <p><b>14.4 V, 10A</b></p> <p>FCC ID : TQ8-ATC32HYAN Contains FCC ID: YZP-VL3000</p> <p>14.4V  10A</p>	<p>HYUNDAI <b>MOBIS</b></p>
	
<p>Made in Korea      Hyundai MOBIS Co., Ltd.</p>	

# Label Information

## 1. Label drawing

Part No. : 96560 P4720



Model : ATC32HCAN

HW ver : 0

**14.4 V, 4  $\Omega$ , 10 A**

FCC ID : TQ8-ATC32HYAN  
Contains FCC ID: YZP-VL3000

14.4V  $\equiv$  10A





Made in Korea

Hyundai MOBIS Co., Ltd.

# Label Information

## 1. Label drawing

<p>Part No. : 96560 P4920</p> <p>Model : ATC35HCAN</p> <p>HW ver : 0</p> <p><b>14.4 V, 4 Ω, 10 A</b></p> <p>FCC ID : TQ8-ATC32HYAN</p> <p>Contains FCC ID: YZP-VL3000</p> <p>14.4V  10A</p>	<p>HYUNDAI</p> <p><b>MOBIS</b></p>
<p>00 3NCJ100009N T014475 00</p> 	
<p>Made in Korea</p> <p>Hyundai MOBIS Co., Ltd.</p>	

## 2. Label location

