To: Roland Gubisch wng@itslabtest.com From: TCB System

FCC Equipment Authorization Branch

Re: FCC ID: LBBFF2150

Applicant:	Continental	Conair Limited
731 Confirmation Nu	umber:	TC993360
Date of Original E-	-Mail:	11/22/2001

FCC TCB Application Error Notification

Errors were found in the following TCB application: Confirmation Number: TC993360 TCB Name: Intertek Testing Services Applicant Name: Continental Conair Limited FCC ID: LBBFF2150 Date of Grant: 10/30/2001 Error Description: Required Exhibit: Cover Letters not received

This is an automated email. When the information indicated in the error message is properly submitted, the message will no longer be sent. Since all information is required within five days of the 'date of grant', the FCC may take additional action if this issue isn't resolved immediately.

Information regarding your application and/or updating your application can be found by accessing www.fcc.gov, E-Filing, OET TCB Electronic Filing.

Do not hit the reply button on this email. For questions about this email, the sender listed above "FCC Equipment Authorization Branch" should be contacted.