

Date: Dec 13, 2022

To Whom It May Concern

Subject: Change ID Request Letter

Applicant: Icom Incorporated

Product: Bluetooth Module

FCC ID: AFJ387300

Dear Sir/Madam

Icom Inc requests a change in the identification of the equipment, as allowed under Part 2.933 of CFR Title 47.

Original FCC ID: VIYHRM1086

Date of original Grant: Nov 8, 2022

Model Name: HRM1086

The new certification for Icom is:

FCC ID: AFJ387300

Model Name: HRM1086

Icom submitted following files electronically as attachments.

1. Cover Letter
2. External Photos

With this request, no changes were applied to module' and 'the original test results continue to be representative of and applicable to the equipment bearing the changed identification.

Should there be any question, please feel free to contact us.

Sincerely,

Icom Incorporated

Atsushi Tomiyama
General Manager of Quality Assurance Department

