


#### 11. **SETUP PHOTOS**

### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





### RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)






### RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION









# POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP


### **EUT POWERED BY AC/DC ADAPTER VIA USB CABLE**





### **EUT POWERED BY HOST PC VIA USB CABLE**





## **END OF REPORT**