





Different Announcement

We declare,

The sample (product name: Multimedia Player Assembly ,model: TR3392/40) and its additional model TR3371/40, TR3361/40 and TR3382/40 are different from appearance design ,GNSS,DAB interface and DAB functions.in addition ,RAM and Storage capacity are the same.

| Product name | Model | Same | Difference Description |
|----------------------------|--------------------|--------------------------|----------------------------------------------|
| Multimedia Player Assembly | TR3392/40(Base) | RAM and Storage capacity | Contains DAB interface and DAB functions |
| | TR3371/40(Variant) | | Contains DAB interface and DAB functions |
| | TR3361/40(Variant) | | not contains DAB interface and DAB functions |
| | TR3382/40(Variant) | | not contains DAB interface and DAB functions |

| Product name | Model | Wireless function | other differences | |
|----------------------------|--------------------|-------------------|----------------------------------------------|---------------------------------------------------------------------------------------|
| | | DAB port | Appearance | |
| Multimedia Player Assembly | TR3392/40(Base) | Y | |  |
| | TR3371/40(Variant) | Y | Mounting bracket is different from TR3392/40 |  |

| | | | | |
|--|--------------------|---|----------------------------------------------|-------------------------------------------------------------------------------------|
| | TR3361/40(Variant) | N | Mounting bracket is different from TR3392/40 |  |
| | TR3382/40(Variant) | N | Mounting bracket is the same as TR3392/40 |  |

Responsible person:

Huizhou Desay SV Automotive Co., Ltd.