

Tough Beacon TB18-2

User Manual

Turning on and maintenance

Kontakt.io Tough Beacons TB18-2 are maintenance-free devices. They work constantly and they are ready to be used in 'out of the box' manner. There is no need to turn the beacon on or activate it in any way. They are ready to perform once programmed and assembled. In case of possible malfunction, their users are advised to contact technical support to receive proper replacements (email: support@kontakt.io). Replacement policy also applies to performance faults caused by low battery after certain operation time. The name of the device and manufacturer are mentioned on the beacons' label.

Installation

Kontakt.io Tough Beacons TB18-2 can be fixed on the wall by using proper screws by means of mounting holes. A user needs to make sure to adhere a Beacon to the mounting surface firmly. Alternatively, one can use double-side adhesive tape and stick it to a flat and smooth surface.

WARNING

Opening beacons or fixing them is strictly forbidden.

Kontakt.io TB18-2 contain electronic elements and batteries which should be properly disposed. If one ever needs to utilize beacons, it is advisable to contact the manufacturer first.

Switching the original battery with one of a different type might cause a risk of explosion.

FCC WARNING

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Any changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

To maintain compliance with FCC's RF Exposure guidelines, This equipment should be installed and operated with minimum 20cm distance between the radiator your body: Use only the supplied antenna.

IC Caution:

RSS-Gen Issue 5 April 2018" & "CNR-Gen 5e April 2018:

- English:

This device complies with Industry Canada licence-exempt RSS standard(s).

Operation is subject to the following two conditions: (1) This device may not cause interference, and (2) This device must accept any interference, including interference that may cause undesired operation of the device.

- French:

Le présent appareil est conforme aux CNR d' Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes:

(1) l'appareil ne doit pas produire de brouillage, et

(2) l' utilisateur de l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.