

To: Sid Sanders  
sid@timcoengr.com  
From: TCB System

FCC Equipment Authorization Branch

Re: FCC ID: LBBGH2410S

Applicant: Continental Conair Limited  
731 Confirmation Number: TC99234  
Date of Original E-Mail: 5/22/2001

FCC TCB Application Error Notification

Errors were found in the following TCB application: Confirmation Number:  
TC99234

TCB Name: Timco Engineering, Inc.

Applicant Name: Continental Conair Limited

FCC ID: LBBGH2410S

Date of Grant: 11/06/2000

Error Description: Required Exhibit: Cover Letters not received

This is an automated email. When the information indicated in the error message is properly submitted, the message will no longer be sent. Since all information is required within five days of the 'date of grant', the FCC may take additional action if this issue isn't resolved immediately.

Information regarding your application and/or updating your application can be found by accessing [www.fcc.gov](http://www.fcc.gov), E-Filing, OET TCB Electronic Filing.

Do not hit the reply button on this email. For questions about this email, the sender listed above "FCC Equipment Authorization Branch" should be contacted.