



Band66-15MHz-16QAM-132322-75RB#0





Band66-15MHz-16QAM-132597-1RB#0





Band66-15MHz-16QAM-132597-75RB#0



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.









Band66-20MHz-QPSK-132322-1RB#0






Band66-20MHz-QPSK-132322-100RB#0




Band66-20MHz-QPSK-132572-1RB#0




Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.





Band66-20MHz-16QAM-132072-1RB#0




Band66-20MHz-16QAM-132072-100RB#0





Band66-20MHz-16QAM-132322-1RB#0





Band66-20MHz-16QAM-132322-100RB#0



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.









Appendix C: 26dB Bandwidth and Occupied Bandwidth

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Occupied Bandwidth (MHz)	26dB Bandwidth (MHz)	Verdict
Band66	1.4MHz	QPSK	131979	6RB#0	1.0921	1.258	PASS
Band66	1.4MHz	QPSK	132322	6RB#0	1.0907	1.267	PASS
Band66	1.4MHz	QPSK	132665	6RB#0	1.0920	1.281	PASS
Band66	1.4MHz	16QAM	131979	6RB#0	1.0919	1.282	PASS
Band66	1.4MHz	16QAM	132322	6RB#0	1.0910	1.272	PASS
Band66	1.4MHz	16QAM	132665	6RB#0	1.0909	1.254	PASS
Band66	3MHz	QPSK	131987	15RB#0	2.6972	2.919	PASS
Band66	3MHz	QPSK	132322	15RB#0	2.6864	2.912	PASS
Band66	3MHz	QPSK	132657	15RB#0	2.6985	2.934	PASS
Band66	3MHz	16QAM	131987	15RB#0	2.6965	2.901	PASS
Band66	3MHz	16QAM	132322	15RB#0	2.6944	2.897	PASS
Band66	3MHz	16QAM	132657	15RB#0	2.6969	2.943	PASS
Band66	5MHz	QPSK	131997	25RB#0	4.5019	4.908	PASS
Band66	5MHz	QPSK	132322	25RB#0	4.4981	4.869	PASS
Band66	5MHz	QPSK	132647	25RB#0	4.5058	4.901	PASS
Band66	5MHz	16QAM	131997	25RB#0	4.5064	4.879	PASS
Band66	5MHz	16QAM	132322	25RB#0	4.5036	4.927	PASS
Band66	5MHz	16QAM	132647	25RB#0	4.5108	4.865	PASS
Band66	10MHz	QPSK	132022	50RB#0	8.9671	9.543	PASS
Band66	10MHz	QPSK	132322	50RB#0	8.9605	9.539	PASS
Band66	10MHz	QPSK	132622	50RB#0	8.9547	9.550	PASS
Band66	10MHz	16QAM	132022	50RB#0	8.9511	9.572	PASS
Band66	10MHz	16QAM	132322	50RB#0	8.9486	9.512	PASS
Band66	10MHz	16QAM	132622	50RB#0	8.9555	9.544	PASS
Band66	15MHz	QPSK	132047	75RB#0	13.424	14.31	PASS
Band66	15MHz	QPSK	132322	75RB#0	13.400	14.23	PASS
Band66	15MHz	QPSK	132597	75RB#0	13.395	14.23	PASS
Band66	15MHz	16QAM	132047	75RB#0	13.415	14.27	PASS
Band66	15MHz	16QAM	132322	75RB#0	13.399	14.25	PASS
Band66	15MHz	16QAM	132597	75RB#0	13.398	14.24	PASS
Band66	20MHz	QPSK	132072	100RB#0	17.872	18.93	PASS
Band66	20MHz	QPSK	132322	100RB#0	17.828	18.94	PASS
Band66	20MHz	QPSK	132572	100RB#0	17.842	18.93	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band66	20MHz	16QAM	132072	100RB#0	17.859	18.94	PASS
Band66	20MHz	16QAM	132322	100RB#0	17.852	18.95	PASS
Band66	20MHz	16QAM	132572	100RB#0	17.845	18.93	PASS

Test Graphs








Band66-1.4MHz-16QAM-131979-6RB#0




Band66-1.4MHz-16QAM-132322-6RB#0




Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.










Band66-3MHz-QPSK-132657-15RB#0



Band66-3MHz-16QAM-131987-15RB#0



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.







Band66-5MHz-QPSK-131997-25RB#0

4:42:28 PM






Band66-5MHz-QPSK-132322-25RB#0




Band66-5MHz-QPSK-132647-25RB#0



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.









Band66-5MHz-16QAM-132647-25RB#0






Band66-10MHz-QPSK-132022-50RB#0





Band66-10MHz-QPSK-132322-50RB#0



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.








Band66-10MHz-16QAM-132322-50RB#0






Band66-10MHz-16QAM-132622-50RB#0




Band66-15MHz-QPSK-132047-75RB#0



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.





Band66-15MHz-16QAM-132047-75RB#0


1 9 6 2 Sep 11, 2023 5:27:33 PM

#Video BW 910.00 kHz*

18.8 dBm 99.00 % -26.00 dB

.:: 🐧





Band66-15MHz-16QAM-132322-75RB#0



Band66-15MHz-16QAM-132597-75RB#0




Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.





Band66-20MHz-QPSK-132572-100RB#0






Band66-20MHz-16QAM-132072-100RB#0




Band66-20MHz-16QAM-132322-100RB#0



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.







Appendix D: Band Edge

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Result(dBm)	Verdict
Band66	1.4MHz	QPSK	131979	1RB#0	-23.44	PASS
Band66	1.4MHz	QPSK	131979	1RB#5	-41.40	PASS
Band66	1.4MHz	QPSK	131979	6RB#0	-29.32	PASS
Band66	1.4MHz	QPSK	132665	1RB#0	-36.77	PASS
Band66	1.4MHz	QPSK	132665	1RB#5	-20.77	PASS
Band66	1.4MHz	QPSK	132665	6RB#0	-24.56	PASS
Band66	1.4MHz	16QAM	131979	1RB#0	-25.55	PASS
Band66	1.4MHz	16QAM	131979	1RB#5	-42.32	PASS
Band66	1.4MHz	16QAM	131979	6RB#0	-30.29	PASS
Band66	1.4MHz	16QAM	132665	1RB#0	-37.05	PASS
Band66	1.4MHz	16QAM	132665	1RB#5	-21.34	PASS
Band66	1.4MHz	16QAM	132665	6RB#0	-23.13	PASS
Band66	3MHz	QPSK	131987	1RB#0	-13.74	PASS
Band66	3MHz	QPSK	131987	1RB#14	-39.16	PASS
Band66	3MHz	QPSK	131987	15RB#0	-21.86	PASS
Band66	3MHz	QPSK	132657	1RB#0	-42.36	PASS
Band66	3MHz	QPSK	132657	1RB#14	-15.97	PASS
Band66	3MHz	QPSK	132657	15RB#0	-23.69	PASS
Band66	3MHz	16QAM	131987	1RB#0	-16.03	PASS
Band66	3MHz	16QAM	131987	1RB#14	-38.78	PASS
Band66	3MHz	16QAM	131987	15RB#0	-22.89	PASS
Band66	3MHz	16QAM	132657	1RB#0	-42.37	PASS
Band66	3MHz	16QAM	132657	1RB#14	-15.11	PASS
Band66	3MHz	16QAM	132657	15RB#0	-25.18	PASS
Band66	5MHz	QPSK	131997	1RB#0	-13.87	PASS
Band66	5MHz	QPSK	131997	1RB#24	-38.39	PASS
Band66	5MHz	QPSK	131997	25RB#0	-22.01	PASS
Band66	5MHz	QPSK	132647	1RB#0	-40.90	PASS
Band66	5MHz	QPSK	132647	1RB#24	-18.13	PASS
Band66	5MHz	QPSK	132647	25RB#0	-24.21	PASS
Band66	5MHz	16QAM	131997	1RB#0	-14.81	PASS
Band66	5MHz	16QAM	131997	1RB#24	-38.87	PASS
Band66	5MHz	16QAM	131997	25RB#0	-22.65	PASS
Band66	5MHz	16QAM	132647	1RB#0	-41.02	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band66	5MHz	16QAM	132647	1RB#24	-19.18	PASS
Band66	5MHz	16QAM	132647	25RB#0	-24.37	PASS
Band66	10MHz	QPSK	132022	1RB#0	-23.09	PASS
Band66	10MHz	QPSK	132022	1RB#49	-36.50	PASS
Band66	10MHz	QPSK	132022	50RB#0	-25.05	PASS
Band66	10MHz	QPSK	132622	1RB#0	-38.86	PASS
Band66	10MHz	QPSK	132622	1RB#49	-23.23	PASS
Band66	10MHz	QPSK	132622	50RB#0	-26.83	PASS
Band66	10MHz	16QAM	132022	1RB#0	-21.49	PASS
Band66	10MHz	16QAM	132022	1RB#49	-36.59	PASS
Band66	10MHz	16QAM	132022	50RB#0	-26.28	PASS
Band66	10MHz	16QAM	132622	1RB#0	-38.93	PASS
Band66	10MHz	16QAM	132622	1RB#49	-24.74	PASS
Band66	10MHz	16QAM	132622	50RB#0	-28.17	PASS
Band66	15MHz	QPSK	132047	1RB#0	-19.28	PASS
Band66	15MHz	QPSK	132047	1RB#74	-35.13	PASS
Band66	15MHz	QPSK	132047	75RB#0	-26.14	PASS
Band66	15MHz	QPSK	132597	1RB#0	-37.45	PASS
Band66	15MHz	QPSK	132597	1RB#74	-23.14	PASS
Band66	15MHz	QPSK	132597	75RB#0	-26.07	PASS
Band66	15MHz	16QAM	132047	1RB#0	-20.19	PASS
Band66	15MHz	16QAM	132047	1RB#74	-34.78	PASS
Band66	15MHz	16QAM	132047	75RB#0	-27.16	PASS
Band66	15MHz	16QAM	132597	1RB#0	-37.26	PASS
Band66	15MHz	16QAM	132597	1RB#74	-23.15	PASS
Band66	15MHz	16QAM	132597	75RB#0	-27.94	PASS
Band66	20MHz	QPSK	132072	1RB#0	-22.73	PASS
Band66	20MHz	QPSK	132072	1RB#99	-34.15	PASS
Band66	20MHz	QPSK	132072	100RB#0	-28.05	PASS
Band66	20MHz	QPSK	132572	1RB#0	-36.62	PASS
Band66	20MHz	QPSK	132572	1RB#99	-25.62	PASS
Band66	20MHz	QPSK	132572	100RB#0	-29.22	PASS
Band66	20MHz	16QAM	132072	1RB#0	-22.76	PASS
Band66	20MHz	16QAM	132072	1RB#99	-34.12	PASS
Band66	20MHz	16QAM	132072	100RB#0	-28.15	PASS
Band66	20MHz	16QAM	132572	1RB#0	-36.60	PASS
Band66	20MHz	16QAM	132572	1RB#99	-25.09	PASS
Band66	20MHz	16QAM	132572	100RB#0	-29.92	PASS



Test Graphs







Band66-1.4MHz-QPSK-132665-1RB#0




Band66-1.4MHz-QPSK-132665-1RB#5



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.










Band66-1.4MHz-16QAM-131979-6RB#0




Band66-1.4MHz-16QAM-132665-1RB#0











Band66-3MHz-QPSK-131987-1RB#14



Band66-3MHz-QPSK-131987-15RB#0



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.