



Intertek Testing Services

ETL SEMKO

Report No.: 03062861
Talk Mode

Tested By: Hong, Report No.: 03062861

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 03062861
Talk Mode

Tested By: Hong, Report No.: 03062861

Scan Settings (1 Range)

Frequencies			Receiver Settings				
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF 60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

3.58500	44.5	56.0
---------	------	------

Frequency	AV Level	AV Limit
MHz	dBuV	dBuV

3.58500	43.1	46.0
---------	------	------

* limit