## FEDERAL COMMUNICATIONS COMMISSION

Laboratory Division 7435 Oakland Mills Road Columbia, MD 21046

June 10, 2015

TUV SUD BABT Octagon House, Concorde Way,, Segensworth North,, Fareham, PO15 5RL United Kingdom

Attention: Hilton Carr

Re: Application Received: 5/31/2015

Equipment Class: JBP-Part 15 Class B Computing Device Peripheral

Applicant Name: TCL Communication Ltd.

FCC ID: 2ACCJB011

TCB Name: TUV SUD BABT

731 Confirmation Number: TC224798

Dear Colleagues:

The application for the above equipment is hereby DISMISSED pursuant to Section 2.917(a) of the Rules for the following reasons.

-----

This application is dismissed because the PCE portion of the composite-application FCC ID is dismissed.

\_\_\_\_\_

If you elect to refile for equipment authorization you must submit a currently dated and originally signed Form 731, accompanied by all data required by the Rule sections applicable to the equipment. The deficiencies listed above must be corrected before refiling. Do not refile the application with the same deficiencies or we may DENY the application pursuant to 2.919. You cannot reuse the FCC ID number on denied applications as you can with dismissed applications. You are cautioned that marketing and importation of equipment in the United States bearing the referenced FCC Identifier is prohibited by Section 2.803 of the Rules. Violation of this regulation may subject you to the penalties provided in Sections 501 and 502 of the Communications Act of 1934, as amended.

Sincerely,

Tim Harrington Electronics Engineer

## FEDERAL COMMUNICATIONS COMMISSION

Laboratory Division 7435 Oakland Mills Road Columbia, MD 21046

June 10, 2015

TCL Communication Ltd. 5F, C-Tower, No.232, Liangjing Road,, Zhangjiang High-tech Park, Pudong, Shanghai China

Attention: Zhizhou Gong

Re: Application Received: 5/31/2015

Equipment Class: JBP-Part 15 Class B Computing Device Peripheral

Applicant Name: TCL Communication Ltd.

FCC ID: 2ACCJB011

TCB Name: TUV SUD BABT

731 Confirmation Number: TC224798

Dear Colleagues:

The application for the above equipment is hereby DISMISSED pursuant to Section 2.917(a) of the Rules for the following reasons.

-----

This application is dismissed because the PCE portion of the composite-application FCC ID is dismissed.

\_\_\_\_\_

If you elect to refile for equipment authorization you must submit a currently dated and originally signed Form 731, accompanied by all data required by the Rule sections applicable to the equipment. The deficiencies listed above must be corrected before refiling. Do not refile the application with the same deficiencies or we may DENY the application pursuant to 2.919. You cannot reuse the FCC ID number on denied applications as you can with dismissed applications. You are cautioned that marketing and importation of equipment in the United States bearing the referenced FCC Identifier is prohibited by Section 2.803 of the Rules. Violation of this regulation may subject you to the penalties provided in Sections 501 and 502 of the Communications Act of 1934, as amended.

Sincerely,

Tim Harrington Electronics Engineer