

Request for Class II Permissive Change

FCC ID: 2AAODBMO700

Date: 23 January 2020

TO: Federal Communication Commission

Please be notified that we, the undersigned, Breville Pty Ltd declare that the reasons for this Class II permissive change are as below:

The difference between the product in original ID and current one is adding alternative one inverter and two IGBT


Before			After		
Part name	Type No.	manufacturer	Part name	Type No.	manufacturer
Inverter	MD-INV200 0-L0S	SONG RESEARCH Electronic Technology CO.,LTD	Inverter	MD-INV20 00-L4	Guangdong Midea Kitchen Appliances Manufacturing Co.,Ltd
IGBT	IHW30N120 R3	Infineon Technologies	IGBT 1	IHW30N13 5R3	Infineon Technologies
			IGBT 2	IHW30N13 5R5	Infineon Technologies

Thank you.
Sincerely,

Name (Printed): John Lee

Title: Compliance Manager

Signature:



JOHN LEE 09/06/2020

On behalf of Company: Breville Pty Ltd