


10. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)








RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION















POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP

EUT POWERED BY AC/DC ADAPTER VIA USB CABLE





EUT POWERED BY HOST PC VIA USB CABLE





END OF REPORT