

Appendix D. SAR Test Setup Photos

Head Exposure Condition



Right Cheek at 0mm



Right Tilted at 0mm



Left Cheek at 0mm



Left Tilted at 0mm

Hotspot Exposure Condition



Front at 10 mm



Back at 10 mm



Right Side at 10 mm



Left Side at 10 mm



Top Side at 10 mm

Body-worn Exposure Condition



Front at 15 mm



Back at 15 mm



Back with Soft Holster at 0 mm

Product Specific Exposure Condition



Front at 0 mm



Back at 0 mm



Right Side at 0 mm



Left Side at 0 mm



Top Side at 0 mm