
10. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)








RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION
















POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP


EUT POWERED BY AC/DC ADAPTER VIA USB CABLE





EUT POWERED BY HOST PC VIA USB CABLE





END OF REPORT