

11 September 2018

Federal Communication Commission  
Equipment Authorization Division, Application Processing Branch  
7435 Oakland Mills Road  
Columbia, MD 21048

Certification and Engineering Bureau  
Industry Canada  
Spectrum Engineering Branch  
3701 Carling Avenue, Building 94  
Ottawa, Ontario K2H 8S2

## **PCII Request / Re-assessment**

**Multiview Media**, FCC ID: <2AJW5MVMDISPLAY > granted on <16/08/2017>  
and IC: <21979-MVMDISPLAY> granted on <18/06/2017>

TO WHOM IT MAY CONCERN

Pursuant to CFR § 2.1043 and RSP-100, <CONTINENTAL AUTOMOTIVE GMBH> hereby requests a Permissive Change Class II / Re-assessment.

Reason:

Improvements within the production process

Modifications:

Change on the PCB:

- Add 2 dampers
- Add additional resistors
- Add solder paste flow arrow (DCR)

Change of the production process:

- integration of Thermal paste station introduction in the assembly line

The following new exhibits will be uploaded:

- Change description document
- Schematics
- Component Layouts

Sincerely,

<SIGNATURE>

<NAME, TITLE> Dr. Marion Gruner ( Homologation Manager)

<COMPANY NAME> CONTINENTAL AUTOMOTIVE GMBH

<ADDRESS> Heinrich-Hertz- Str. 45, 78052 Villingen- schwenningen, Germany

<PHONE NO.>+ 49 7721/ 67 2802

