To: Yuna Yin cb@vista-compliance.com From: Stan Lyles Stanley.Lyles@fcc.gov FCC Equipment Authorization Branch

Re: FCC ID: 2A482-PPCXZ1002

Applicant:	Shenzhen Baseus Technology Co., Ltd.
Correspondence Number:	560964
731 Confirmation Number:	TC953414
Date of Original E-Mail:	07/05/2023

Subject: FCC Equipment Authorization System

Please correct the attestation for US Agent for Service of Process to include the correct FCC address of the US Agent for all 3 letter . See below. Attestation statement letter 1 and 2 and the USA Agent of Service for Process Letter.

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal pursuant to Section 2.917(c).

DO NOT Reply to this email by using the Reply button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <u>https://apps.fcc.gov/tcb.</u> TCB Login, Submit Correspondence. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

To: Zhang Mao zhangmao@baseus.com From: Stan Lyles Stanley.Lyles@fcc.gov FCC Equipment Authorization Branch

Re: FCC ID: 2A482-PPCXZ1002

Applicant:	Shenzhen Baseus Technology Co., Ltd.
Correspondence Number:	560965
731 Confirmation Number:	TC953414
Date of Original E-Mail:	07/05/2023

Subject: FCC Equipment Authorization System

Please correct the attestation for US Agent for Service of Process to include the correct FCC address of the US Agent for all 3 letter . See below. Attestation statement letter 1 and 2 and the USA Agent of Service for Process Letter.

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal pursuant to Section 2.917(c).

DO NOT Reply to this email by using the Reply button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <u>https://apps.fcc.gov/tcb.</u> TCB Login, Submit Correspondence. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.