


FUNAI ELECTRIC CO., LTD.	
DEPT. TV Engineering Dept.	DEV. TV Engineering Dept.
DATE 99.12.14	SCALE 1/10
DESIGNER	CHECKER
APPROVED	APPROVED
TITLE Z8 HV/CRT	
PARTS NO.	
DRAWING NO.	

ISSUED
DEC. 16, 1998
FUNAI ELECTRIC CO., LTD.
Lab.




		FUNAI ELECTRIC CO., LTD.	
部局 DEPT.	工程技術部 TV Engineering Dept.	表題 TITLE	Z8 HV/CRT
作成日 DATE	98.12.14 SCALE	製品品番 PARTS NO.	
作成 DRAWN	設計 DESIGNED	検査 CHECKED	承認 APPROVED
DRAWN DESIGNED CHECKED APPROVED		図面番号 DWG. NO.	

ISSUED
 DEC. 16, 1998
 FUNAI ELECTRIC CO., LTD.
 Lab.

WARNING: Replacement parts with special safety characteristics are identified by a **⚠** (exclamation mark within equilateral triangle) showing on the schematic diagram. Replace these critical components with recommended replacement parts only. Improper servicing, degrade the safety of this appliance through improper servicing. Service personnel should make leakage-current or resistance measurements to determine that exposed bare parts are acceptably insulated from the supply circuit before returning the appliance to the customer.

CAUTION PROTECT AGAINST FIRE AND ELECTRICAL SHOCK. DO NOT TOUCH THE REFRIGERATOR COMPRESSOR OR THE REFRIGERANT LINES. REFRIGERANT IS UNDER HIGH PRESSURE AND MAY BE VERY HOT.

POCEC



⚠
NON-INDICATIVE

⚠
NON-INDICATIVE

⚠
NON-INDICATIVE

