Project No. : SE-01-0723

# 2. System Test Configuration

### 2.1 Configuration of Radiated and Conducted Interference Measurement

\* Cabling was taken into consideration and test data was taken under worse case conditions.

#### 1)Conduction(Front View)




### 2)Conduction(Rear View)





# 3) Radiation(Front View)



# 4) Radiation(Rear View)

