


Report No. : EED32O81173004




Page 54 of 57





Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)






Report No. : EED32O81173004





Page 55 of 57



Radiated spurious emission Test Setup-3(Above 18GHz)



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.
















Hotline:400-6788-333 www.cti-cert.com E-mail:info@cti-cert.com Complaint call:0755-33681700 Complaint E-mail:complaint@cti-cert.com



Report No. : EED32O81173004



Page 57 of 57

## PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32O81173001 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

